



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI SE NAV
Colour	White
Year of manufacture	2014
Top speed	112 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	145 g/km
CO2 label	F







Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-02
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	21
Total items failed	2

MOT #10	2024-02-26 11:42
MOT test number	135716428937
Result	✓ Passed
Next expiry date	2025-03-02

MOT #9	2023-03-03 13:55
MOT test number	103352245032
Result	✓ Passed

- Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #8** 2023-02-27 10:39**MOT test number** 887940779979**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Front Tyre pressure monitoring system malfunctioning or obviously inoperative sensor missing (5.2.3 (h))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))**MOT #7** 2022-02-28 15:54**MOT test number** 475657868787**Result** ✓ Passed**MOT #6** 2021-02-26 13:39**MOT test number** 430894363534**Result** ✓ Passed**MOT #5** 2020-11-24 09:27**MOT test number** 262968294332**Result** ✓ Passed**Advice** Oil leak, but not excessive transmission (8.4.1 (a) (i))

**MOT #4** 2020-11-24 09:27**MOT test number** 869473338214**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**Advice** Oil leak, but not excessive transmission (8.4.1 (a) (i))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**MOT #3** 2019-11-14 13:04**MOT test number** 636751305947**Result** ✓ Passed**Advice** Oil leak, but not excessive transmission (8.4.1 (a) (i))**MOT #2** 2018-11-19 10:46**MOT test number** 839710915205**Result** ✓ Passed**MOT #1** 2017-11-14 11:41**MOT test number** 159224728125**Result** ✓ Passed**Advice** Offside indicator repeater lamp slightly damaged.**Advice** Offside Side repeater has light sources not illuminating, but not more than 50% (1.4.A.2c)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
2 March 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	2 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-11-27
Last registration	2024-02-26
Complete history	See info



Registration #1	2014-11-27	8 mi
Registration #2	2017-11-14	57.761 mi
Registration #3	2018-11-19	70.978 mi
Registration #4	2019-11-14	78.814 mi
Registration #5	2020-11-24	83.298 mi
Registration #6	2020-11-24	83.298 mi
Registration #7	2020-11-24	83.298 mi
Registration #8	2020-11-24	83.298 mi
Registration #9	2020-11-24	83.298 mi
Registration #10	2020-11-24	83.298 mi
Registration #11	2020-11-24	83.298 mi
Registration #12	2020-11-24	83.298 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1679 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4HAEZ081390