





report date: 2024-03-29

General information

Make	BMW
Model	X3 XDRIVE20D SE
Colour	Silver
Year of manufacture	2016
Top speed	130 mph
0 - 60 mph	8.1 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	190 BHP
Max. torque	400 Nm at 2.500 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	60.1 mpg
Consumption combined	57.6 mpg
CO2 emission	136 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 2

Date 2021-08-10

Pictures 26

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2021-06-12

Pictures 28

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

N/I	α		uc:	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2024-11-08
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	21
Total items failed	2

MOT #7	2023-11-09 16:17
MOT test number	538463904594
Result	✓ Passed
Next expiry date	2024-11-08
Advice Engine cover fitted, under trays fitted.	
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #6 2023-11-08 17:34

MOT test number 213990696737

Result X Failed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Engine cover fitted, under trays fitted.

Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #5 2022-10-18 09:57

MOT test number 944737478720

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge Has a cut but not deep enough to reach the ply or cords (5.2.3 (e))

Advice Offside Front Play in steering rack inner joint(s)

Advice Offside Rear Tyre worn close to legal limit/worn on edge Has a cut but not deep enough to reach the ply or cords (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge Has a cut but not deep enough to reach the ply or cords (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Has a cut but not deep enough to reach the ply or cords (5.2.3 (e))

MOT #4 2021-06-10 08:23

MOT test number 909632730515

CarCheck.co.uk page 4/12



Advice

LC66ZFW

report date: 2024-03-29

MOT #3

MOT test number

525732857503

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2

MOT test number

Fesult

Advice Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1

MOT test number

Result

Advice Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 5/12



LC66ZFW report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	8 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



faste since

LC66ZFW

report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this BMW had different number plates.

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-11-30
Last registration	2023-11-09
Complete history	See info



Registration #1	2016-11-30	8 mi
Registration #2	2019-11-27	23.759 mi
Registration #3	2019-11-28	23.831 mi
Registration #4	2020-11-24	32.682 mi
Registration #5	2021-06-10	35.221 mi
Registration #6		11.777 es
Registration #6 Registration #7		11.777 es
-		11.77 m
Registration #7		11.77 es 11.77 es 11.77 es

More info >

CarCheck.co.uk page 11/12



LC66ZFW report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	88%
Children	83%
Pedestrian	53%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	2089 mm
Height	1678 mm
Length	4657 mm
Wheel base	2810 mm
Kerb weight	1745 kg
Max. allowed weight	2365 kg

Additional information

Fuel tank capacity	67 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	age 12/12