





report date: 2024-03-29

### General information

Make	BMW
Model	Z4 Z4 SDRIVE20I M SPORT ROADSTER
Colour	Black
Year of manufacture	2016
Top speed	146 mph
0 - 60 mph	6.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	181 BHP
Max. torque	270 Nm at 1.250 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/11



**KN660TF** 

report date: 2024-03-29

## Internet history

#### Entry 2

Date	2022-10-31
Pictures	1

Listing price <u>View report</u>



source: autoonline.co.uk

#### Entry 1

Date	2022-05-22	
Pictures	12	
Listing price	View report	









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-08-31
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	5
Total items failed	3

MOT #7	2023-08-27 10:39
MOT test number	254443155094
Result	✓ Passed
Next expiry date	2024-08-31

MOT #6	2022-09-01 09:21
MOT test number	636689172080
Result	<b>✓</b> Passed

MOT #5	2021-09-01 09:16
MOT test number	714193301504
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4		2021-08-28 09:13
MOT test number		346080498165
Result		<b>×</b> Failed
<b>Advice</b> Nearside Re	ear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear	r Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Nearside Rear E	Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #3

MOT test number

Result

Advice Nearside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))

 MOT #2
 2019-09-27 15:34

 MOT test number
 297684728173

 Result
 ✓ Passed

MOT test number

Result

Fail Offside Rear Inner Road wheel fractured Inner rim is cracked (5.2.2 (a))

Advice Offside Front Inner Nail in tyre Puncture on inner edge of tread

Fail Nearside Rear Road wheel fractured Inner rim is cracked in two places. (5.2.2 (a))

CarCheck.co.uk page 4/11



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	31 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

## Owner history

e mier metery	
For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report I	
**************************************	
************	
manage of the same	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Exercised contributions	NIZ (
Carried region and	UK UK
Plate since	
Current registration	OK SIE
	ŪK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



**KN660TF** 

report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-09-24
Last registration	2023-08-27
Complete history	See info



Registration #1	2016-09-24	12 mi
Registration #2	2019-09-13	30.864 mi
Registration #3	2019-09-27	30.873 mi
Registration #4	2020-07-23	33.945 mi
Registration #5	2021-08-28	37.348 mi
Registration #6		11.777 es
		11.777 ea 11.777 ea
Registration #6		1.77 m
Registration #6 Registration #7		11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 10/11



**KN660TF** 

report date: 2024-03-29

## Car features

50225	Air conditionin
50295	
60482	
60501	
0566	
0567	
60569	

# Safety ratings

NCAP rating	***
Adult	69%
Children	61%
Pedestrian	91%
Safety systems	46%
Overall rating	67%
Video	see crash video



# Dimensions & weight

Width	1790 mm
Height	1291 mm
Length	4239 mm
Wheel base	2496 mm
Kerb weight	1395 kg
Max. allowed weight	1725 kg

# Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	2 page 11/1

Number of axles 2

**Engine number** A5531414