



report date: 2024-03-29

General information

Make	FIAT
Model	PANDA TWINAIR LOUNGE
Colour	Red
Year of manufacture	2016
Top speed	117 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	145 Nm at 2.000 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	80.7 mpg
Consumption combined	67.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 4

Date	2023-06-05
Pictures	0
Listing price	<a href="#">View report</a>

source: carcraft.co.uk

Entry 3

Date	2023-03-22
Pictures	0
Listing price	<a href="#">View report</a>

source: carcraft.co.uk

Entry 2

Date	2022-11-14
Pictures	0
Listing price	<a href="#">View report</a>

source: carcraft.co.uk

Entry 1

Date	2022-05-15
Pictures	29
Listing price	<a href="#">View report</a>



source: yesauto.com



## MOT history

MOT expiry date	2024-07-24
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	1
Total items failed	6

MOT #9	2023-07-25 11:55
MOT test number	940738025721
Result	✓ Passed
Next expiry date	2024-07-24

MOT #8	2023-02-22 10:20
MOT test number	800653917139
Result	✓ Passed

MOT #7	2022-02-01 10:21
MOT test number	679678484126
Result	✓ Passed

MOT #6	2022-02-01 10:21
MOT test number	474992379958
Result	✗ Failed
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))

MOT #5	2021-02-23 12:12
MOT test number	729832488979
Result	✓ Passed

**MOT #4** 2020-10-19 10:54**MOT test number** 599375146146**Result** ✓ Passed**MOT #3** 2020-10-19 08:14**MOT test number** 439773102361**Result** ✗ Failed**Fail** Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #2** 2019-02-13 12:12**MOT test number** 208465036837**Result** ✓ Passed**MOT #1** 2019-02-13 12:12**MOT test number** 830464779053**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too low head light aim to low (4.1.2 (a))**Pass with rectification** Offside Front Headlamp aim too low head light aim to low (4.1.2 (a))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
24 July 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	24 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2016-03-01
Last registration	2023-07-25
Complete history	<a href="#">See info</a>



Registration #1	2016-03-01	8 mi
Registration #2	2019-02-13	9.306 mi
Registration #3	2019-02-13	9.306 mi
Registration #4	2020-10-19	22.937 mi
Registration #5	2020-10-19	22.937 mi
Registration #6	2021-02-23	23.248 mi
Registration #7	2022-02-01	23.656 mi
Registration #8	2023-07-25	23.777 mi
Registration #9	2023-07-25	23.777 mi
Registration #10	2023-07-25	23.777 mi
Registration #11	2023-07-25	23.777 mi
Registration #12	2023-07-25	23.777 mi
Registration #13	2023-07-25	23.777 mi
Registration #14	2023-07-25	23.777 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3571 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1380 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	0343938