





### General information

Make	VOLKSWAGEN	
Model	AMAROK DC TDI TRENDLINE 4MOTION	
Colour	Silver	
Year of manufacture	2012	
Top speed	112 mph	
0 - 60 mph	11.1 seconds	
Gearbox	6 speed Manual	

### Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	40.4 mpg
Consumption combined	35.8 mpg
CO2 emission	209 g/km
CO2 label	K







Internet history	
Entry 1	
Date	2021-08-30
Pictures	0
Listing price	View report

source: autotrader.co.uk



# MOT history

MOT expiry date	2024-09-29
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	17
Total items failed	5

MOT #11	2023-09-13 13:23
MOT test number	216941801453
Result	✓ Passed
Next expiry date	2024-09-29

MOT #10		2022-09-07 13:24
MOT test	number	740741328646
Result		✓ Passed
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

МОТ #9	2021-09-04 15:02
MOT test number	334003452925
Result	✓ Passed
<b>Advice</b> Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #8	2020-09-30 10:44
MOT test	<b>number</b> 483290651516
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))





MOT #7	2020-09-30 10:44	
MOT test number	904869741543	
Result	× Failed	
Minor Windscreen dama	aged but not adversely affecting driver's view (3.2 (a) (i))	
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))		
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))	

MOT #6		2019-08-20 08:16
MOT test	number	515450169020
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2019-08-20 08:16	
MOT test number	925182993907	
Result	× Failed	
Pass with rectification	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice Offside Rear Tyre	e worn close to legal limit/worn on edge (5.2.3 (e))	

МОТ #4	2018-10-10 09:25
MOT test number	920696966348
Result	✓ Passed
Advice Handbrake could be better	





MOT #3		2017-09-20 14:19
MOT test	number	523298514119
Result		✓ Passed
Advice	Emissions to clean to register & revs limited	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1	a)
Advice	O/S/F Day running light inop:	

MOT #2		2016-09-05 13:46
MOT test	number	879062758992
Result		✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.	.3.1d)
Advice	Unable to read emissions on emissions testing machine due being to clean regi	ster

MOT #1	2015-08-21 10:28
MOT test number	515983835281
Result	✓ Passed



Tax & MOT check

✓ Taxed	✓ MOT Expires: 29 September 2024
1 April 2025 Tax status	29 September 2024 Valid until 1 April
Days left	336
MOT expiry date	29 September 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-





#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FETTOR
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Date	OLE .
Category	AM
Туре	

#### Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700





### Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

***********	
*********	
**********	
NUMBER OF CONTRACTOR OF CONTRA	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Current registration	
Plate since	
Current registration	
Reds sizes	





#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-09-01
Last registration	2023-09-13
Complete history	<u>See info</u>



Registration #1	2012-09-01	7 mi
Registration #2	2015-08-21	39.974 mi
Registration #3	2016-09-05	59.213 mi
Registration #4	2017-09-20	78.707 mi
Registration #5	2018-10-10	102.372 mi
Registration #6	2019-08-20	137.298 mi
Registration #7	2019-08-20	137.298 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		10.200 est





# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	
Adult	86%
Children	64%
Pedestrian	47%
Safety systems	57%
Overall rating	71%
Video	see crash video



Dimensions & weight	
Width	2228 mm
Height	1834 mm
Length	5254 mm
Kerb weight	2065 kg
Max. allowed weight	3170 kg
Additional information	
Fuel tank capacity	80 I

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
CarCheck.co.uk	page 12/12