



report date: 2024-03-28

General information

Make	FORD
Model	FOCUS C-MAX ZETEC
Colour	Silver
Year of manufacture	-
Top speed	120 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	166 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-24
Pictures	3
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #21** 2022-09-22 10:33**MOT test number** 857965277437**Result** ✓ Passed**Next expiry date** 2023-10-17

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush worn (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush worn (5.3.4 (a) (i))

MOT #20 2021-10-11 11:27**MOT test number** 148214324980**Result** ✓ Passed**MOT #19** 2020-10-12 10:05**MOT test number** 899195652570**Result** ✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
rear bush (5.3.4 (a) (i))

Minor Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
rear bush (5.3.4 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #18 2019-10-18 11:27**MOT test number** 305112409999**Result** ✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
rear bush (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
rear bush (5.3.4 (a) (i))

MOT #17

2018-07-31 14:47

MOT test number

596267310393

Result

✓ Passed



MOT #16	2018-07-27 09:42
MOT test number	653514632850
Result	✗ Failed
MAJOR	Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
MAJOR	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #15	2017-07-28 07:56
MOT test number	284879000332
Result	✓ Passed
Advice	Nearside Rear Nail in tyre
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)
Advice	Offside Front Inner tyre wall cut no cords
Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #14**

2017-07-27 14:35

MOT test number

209259787458

Result**✗ Failed**

- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Fail** Nearside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Fail** Offside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Offside Front Inner tyre wall cut no cords
- Advice** Nearside Rear Nail in tyre

MOT #13

2016-08-01 16:24

MOT test number

662557269088

Result**✓ Passed****MOT #12**

2016-07-29 12:11

MOT test number

539918984701

Result**✗ Failed**

- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

**MOT #11** 2015-07-15 13:02**MOT test number** 235846995188**Result** ✓ Passed**Notice** Offside rear tyre getting low on inner edge**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #10** 2015-07-15 12:19**MOT test number** 798786995189**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Offside Stop lamp not working (1.2.1b)**Notice** Offside rear tyre getting low on inner edge**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**MOT #9** 2014-07-09 16:30**MOT test number** 477610094154**Result** ✓ Passed**MOT #8** 2013-07-17 10:32**MOT test number** 927768093179**Result** ✓ Passed**MOT #7** 2012-08-20 12:14**MOT test number** 477583632250**Result** ✓ Passed**Advice** Front Headlamp damaged but light output not reduced (1.7.5a)**Advice** Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)

**MOT #6** 2011-09-01 10:33**MOT test number** 369994941286**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**MOT #5** 2010-09-07 13:13**MOT test number** 422420750266**Result** ✓ Passed**MOT #4** 2009-09-04 14:40**MOT test number** 771987449224**Result** ✓ Passed**MOT #3** 2008-09-11 11:13**MOT test number** 863765558201**Result** ✓ Passed**MOT #2** 2007-09-06 09:54**MOT test number** 491129047298**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Seat belt damaged but not affecting the operation of the belt (5.2.2a)**Notice** N/s door mirror taped on**MOT #1** 2006-08-29 12:57**MOT test number** 450871346204**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	AK53GGU
Plate since	2019-03-28
Current registration	AK53GGU
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2003-09-11
Last registration	2022-09-22
Complete history	See info



Registration #1	2003-09-11	12 mi
Registration #2	2006-08-29	24.611 mi
Registration #3	2007-09-06	31.411 mi
Registration #4	2008-09-11	35.297 mi
Registration #5	2009-09-04	40.095 mi
Registration #6	2010-09-07	44.668 mi
Registration #7	2011-09-01	48.504 mi
Registration #8	2012-08-20	53.200 mi
Registration #9	2013-07-17	56.135 mi
Registration #10	2014-07-09	61.435 mi
Registration #11	2015-07-15	63.504 mi
Registration #12	2015-07-15	63.504 mi
Registration #13	2016-07-15	63.504 mi
Registration #14	2017-07-15	63.504 mi
Registration #15	2018-07-15	63.504 mi
Registration #16	2019-07-15	63.504 mi
Registration #17	2020-07-15	63.504 mi
Registration #18	2021-07-15	63.504 mi
Registration #19	2022-07-15	63.504 mi
Registration #20	2023-07-15	63.504 mi
Registration #21	2024-07-15	63.504 mi
Registration #22	2025-07-15	63.504 mi
Registration #23	2026-07-15	63.504 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1783 mm
Height	1558 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1422 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	3J46305