



report date: 2024-03-29

General information

Make	KIA
Model	SORENTO CRDI KX-3
Colour	Black
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
CO2 emission	177 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-07-08
Pictures	9
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-03-06
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	19
Total items failed	7

MOT #132024-03-04 11:26

MOT test number783663735077

Result✓ Passed

Next expiry date2025-03-06

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #122023-02-28 18:23

MOT test number555231350915

Result✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #112023-02-27 10:08

MOT test number791382926485

Result✗ Failed

Fail Nearside Rear Inner Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))**Fail** Offside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2022-03-07 11:46**MOT test number** 753241202253**Result** ✓ Passed**MOT #9** 2022-02-09 10:14**MOT test number** 899011715324**Result** ✗ Failed

Fail Nearside Rear Vehicle structure is so weakened by corrosion within 30cm of a towbar mounting, the towbar is likely to become detached (6.1.6 (i) (ii))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Rear Towbar with an unsafe modification to primary components corroded to excess (6.1.6 (g) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Offside Rear Vehicle structure is so weakened by corrosion within 30cm of a towbar mounting, the towbar is likely to become detached (6.1.6 (i) (ii))

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Coil spring corroded all four springs (5.3.1 (b) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #8 2020-10-16 15:46**MOT test number** 719420288597**Result** ✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

MOT #7 2019-09-30 16:49**MOT test number** 663592921221**Result** ✓ Passed

**MOT #6** 2018-10-23 10:04**MOT test number** 568251837256**Result** ✓ Passed**MOT #5** 2018-08-27 09:57**MOT test number** 184507836950**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened Both fronts (1.1.14 (a) (ii))**Advice** Towbar slightly corroded within 30cm of towbar mounting (6.1.6 (i) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened Both rears (1.1.14 (a) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #4** 2017-08-11 15:06**MOT test number** 464675105334**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2016-08-23 11:07**MOT test number** 950501041849**Result** ✓ Passed**Advice** Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2015-08-27 16:43**MOT test number** 375899035498**Result** ✓ Passed



MOT #1	2014-08-28 10:27
MOT test number	117310344228
Result	✓ Passed
<div>Advice</div> Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
6 March 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	6 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	SA61GVY
Plate since	2019-03-29
Current registration	SA61GVY
Plate since	2019-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-01
Last registration	2024-03-04
Complete history	See info



Registration #1	2011-09-01	18 mi
Registration #2	2014-08-28	36.650 mi
Registration #3	2015-08-27	46.672 mi
Registration #4	2016-08-23	50.435 mi
Registration #5	2017-08-11	55.839 mi
Registration #6	2018-08-27	63.403 mi
Registration #7	2018-10-23	64.294 mi
Registration #8	2019-09-30	74.528 mi
Registration #9	2020-09-30	85.277 mi
Registration #10	2021-09-30	96.026 mi
Registration #11	2022-09-30	106.775 mi
Registration #12	2023-09-30	117.524 mi
Registration #13	2024-03-04	128.273 mi
Registration #14		
Registration #15		

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	84%
Pedestrian	44%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1885 mm
Height	1755 mm
Length	4685 mm
Wheel base	2700 mm
Kerb weight	1896 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

D4HBBH023291