





## General information

Make	AUDI
Model	TT TFSI
Colour	Black
Year of manufacture	2008
Top speed	149 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	200 BHP
Max. torque	280 Nm at 1.800 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	183 g/km
CO2 label	I





## Internet history

Entry 1

Date

Pictures

2021-05-24

2

coming Soon

Listing price

View report



source: autotrader.co.uk



# MOT history

MOT expiry date	2024-12-09
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	42
Total items failed	7

MOT #17	2023-12-05 12:27
MOT test number	623452261647
Result	✓ Passed
Next expiry date	2024-12-09
Minor Offside Front Outer Drive shaft joint constant velocity boot severely deter	eriorated (6.1.7 (g) (i))
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Minor Offside Windscreen wiper blade defective (3.4 (b) (i))	
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #16		2023-12-05 12:27
MOT test number		991718694561
Result		🗙 Failed
Minor Offside Front Out	er Drive shaft joint constant velocity boot severely	deteriorated (6.1.7 (g) (i))
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))		
<b>Pass with rectification</b> Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b)		
(ii))		
Minor Offside Windscreen wiper blade defective (3.4 (b) (i))		
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))		
Advice Nearside Rear C	oil spring corroded (5.3.1 (b) (i))	



<b>AP08CXX</b>
report date: 2024-03-28

MOT #15		2022-12-06 16:42
MOT #15 MOT test		619821284715
	number	
Result		✓ Passed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6	5.1.7 (g) (i))
NOT #14		2022 12 05 10.12
MOT #14		2022-12-05 18:12
MOT test	number	301415751528
Result		🗙 Failed
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
<b>Fail</b> (5.3.4 (b)	Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the in (ii))	ngress of dirt
<b>Fail</b> C	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6	5.1.7 (g) (i))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
<b>Fail</b> Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))		

Advice Nearside Rear Tyre worn close to legal limit/worn on edge badly worn inner edge 2.0mm (5.2.3 (e))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #13	2021-12-10 17:0	5
MOT test	number 69427609760	4
Result	✓ Passe	b
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	



MOT #12	2021-12-08 15:48
MOT test number	918439324937
Result	🗙 Failed
<b>Fail</b> Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	
<b>Fail</b> Offside Rear fog lamp not working (4.5.1 (a) (ii))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.)	14 (a) (ii))

MOT #11		2020-08-25 13:25
MOT test	number	389094101418
Result		✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	
Advice Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e)) Play in o.s f rack end / play in o.s.f link arm	

MOT #10		2019-05-04 09:47
MOT test	number	931724311946
Result		✓ Passed
Advice	Nearside Front Tyre rim protector damaged	
Advice	Nearside Front Tyre close to wear indicators	

MOT #9		2018-05-10 15:06
MOT test	number	810368041935
Result		✓ Passed
Advice	Rear brake pads low	
Advice	Brake fluid contamination	

**AP08CXX** 

report date: 2024-03-28





MOT #8		2017-05-11 09:22
MOT test i	number	528591432186
Result		✓ Passed
MOT #7		2016-04-29 11:50
MOT test I	number	319983144819
Result		✓ Passed
Advice	Top and lower engine covers fitted not allowing full inspection	
Advice	O/s/f tyre worn low	
MOT #6		2015-05-06 15:16
MOT test i	number	318066125130
Result		✓ Passed

Advice	Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b> (2.4.G.2)	Offside Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt

MOT #5		2014-05-19 11:47
MOT test	number	416769734186
Result		✓ Passed
Notice	Slight outter side wall damage to n/s/r tyre	
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Both rear tyres worn low 255/35r19y	
Notice	Under-trays fitted obscuring some underside components	





MOT #4	2014-05-16 15:47
MOT test number	328946834173
Result	🗙 Failed
<b>Notice</b> Under-trays fitted obscuring some underside components	
<b>Notice</b> Slight outter side wall damage to n/s/r tyre	
Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
<b>Notice</b> Engine covers fitted obscuring some components in the engine bay	
Notice Both rear tyres worn low 255/35r19y	
MOT #3	2013-05-16 16:22

MOT test number	216056833471
Result	✓ Passed

MOT #2	2012-05-11 15:01
MOT test number	279982132409
Result	✓ Passed

MOT #1	2011-05-17 12:22
MOT test number	249907931192
Result	✓ Passed



Tax & MOT check

<b>Taxed</b> <b>Tax due:</b> 1 December 2024	✓ MOT Expires: 9 December 2024
Tax status	Valid until 1 December
Days left	217
MOT expiry date	9 December 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





#### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	e et al
Date	*
Category	AMP
Туре	

#### Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
***********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





## Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-05-19
Last registration	2023-12-05
Complete history	<u>See info</u>



Registration #1	2008-05-19	14 mi
Registration #2	2011-05-17	74.653 mi
Registration #3	2012-05-11	78.433 mi
Registration #4	2013-05-16	79.964 mi
Registration #5	2014-05-16	87.496 mi
Registration #6	2014-05-19	87.496 mi
Registration #7	2015-05-06	93.423 mi
Registration #8	2016-04-29	98.421 mi
Registration #9	2017-05-11	104.413 mi
Registration #10	2018-05-10	110.329 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		10.000 est





### Car features

S0225	Air conditioning
S0295	
S0482	
\$0501	
\$0566	
\$0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1842 mm
Height	1352 mm
Length	4178 mm
Wheel base	2468 mm
Kerb weight	1260 kg
Max. allowed weight	1660 kg
Additional information	
Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 14/14

Number of axles	2
Engine number	BWA 230608