



General information

Make	FORD
Model	FOCUS TITANIUM
Colour	Blue
Year of manufacture	2010
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	149 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 2

Date	2021-07-03
Pictures	9
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-12
Pictures	9
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-31
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	27
Total items failed	8

MOT #15	2023-08-31 09:46
MOT test number	308975946472
Result	✓ Passed
Next expiry date	2024-08-31
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #14	2023-08-29 14:40
MOT test number	565954896375
Result	✗ Failed
Fail	Front Position lamp not working Both (4.2.1 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #13** 2022-08-26 11:01**MOT test number** 775563614431**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing 205/55x16 (5.2.3 (d) (ii))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge 205/55x16 (5.2.3 (e))**MOT #12** 2021-09-01 15:17**MOT test number** 520525102974**Result** ✓ Passed**MOT #11** 2020-11-12 16:57**MOT test number** 700833514430**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10** 2019-12-09 12:33**MOT test number** 785667938326**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #9** 2019-12-06 10:46**MOT test number** 595089439505**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively pads low (1.1.14 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Registration plate insecure but not likely to fall off (0.1 (a))**MOT #8** 2018-11-15 12:49**MOT test number** 344089162098**Result** ✓ Passed**MOT #7** 2017-12-06 16:00**MOT test number** 896127759297**Result** ✓ Passed**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit worn on inner edge (4.1.E.1)**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit bald on inner edge (4.1.E.1)

**MOT #6**

2017-12-06 16:00

MOT test number

149306458291

Result**✗ Failed****Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Tyre worn close to the legal limit worn on inner edge (4.1.E.1)**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Offside Front Tyre worn close to the legal limit bald on inner edge (4.1.E.1)**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #5**

2016-07-14 11:23

MOT test number

409882357598

Result**✓ Passed****Advice** Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4**

2015-07-17 16:42

MOT test number

359418295123

Result**✓ Passed****Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3**

2015-07-17 13:55

MOT test number

705218795107

Result**✗ Failed****Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #2	2014-07-18 15:43
MOT test number	529839294122
Result	✓ Passed

MOT #1	2013-07-18 13:52
MOT test number	277739693153
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
31 August 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	31 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-31
Last registration	2023-08-31
Complete history	See info



Registration #1	2010-03-31	17 mi
Registration #2	2013-07-18	66.975 mi
Registration #3	2014-07-18	81.277 mi
Registration #4	2015-07-17	93.216 mi
Registration #5	2015-07-17	93.216 mi
Registration #6	2016-07-14	98.221 mi
Registration #7	2017-12-06	107.667 mi
Registration #8	2017-12-06	107.667 mi
Registration #9	2018-11-15	113.487 mi
Registration #10	2019-05-20	121.277 mi
Registration #11	2019-05-20	121.277 mi
Registration #12	2019-05-20	121.277 mi
Registration #13	2019-05-20	121.277 mi
Registration #14	2019-05-20	121.277 mi
Registration #15	2019-05-20	121.277 mi
Registration #16	2019-05-20	121.277 mi
Registration #17	2019-05-20	121.277 mi
Registration #18	2019-05-20	121.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1249 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AS14346