



Mercedes-Benz



report date: 2024-03-29

General information

| | |
|---------------------|------------------------|
| Make | MERCEDES |
| Model | SLK SLK 200 KOMPRESSOR |
| Colour | Black |
| Year of manufacture | 2009 |
| Top speed | 155 mph |
| Gearbox | 7 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 184 BHP |
| Max. torque | 250 Nm at 2.800 rpm |
| Engine capacity | 1.796 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 23.9 mpg |
| Consumption extra urban | 45.6 mpg |
| Consumption combined | 34.5 mpg |
| CO2 emission | 196 g/km |
| CO2 label | J |





Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2023-09-02 |
| Pictures | 12 |
| Listing price | View report |



source: cargurus.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-05 |
| Pictures | 11 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2023-08-21 |
| MOT pass rate | 92 % |
| MOT passed | 11 |
| Failed MOT tests | 1 |
| Total advice items | 19 |
| Total items failed | 1 |

MOT #12 2022-08-11 11:03

MOT test number 721029999211

Result ✓ Passed

Next expiry date 2023-08-21

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))

MOT #11 2021-08-16 10:04

MOT test number 630509280573

Result ✓ Passed

- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))

**MOT #10** 2020-08-10 14:08**MOT test number** 177496885649**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #9** 2019-08-05 09:55**MOT test number** 677362228456**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))**MOT #8** 2018-08-20 09:39**MOT test number** 760411068449**Result** ✓ Passed**MOT #7** 2017-08-22 15:56**MOT test number** 784731114347**Result** ✓ Passed**Advice** Nearside PARKING BRAKE ISN'T GREAT

**MOT #6** 2017-08-11 08:39**MOT test number** 505454103111**Result** ✗ Failed**Advice** Nearside PARKING BRAKE ISN'T GREAT**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** BOTH REAR TYRES ARE WORN ON THE EDGES**MOT #5** 2016-08-15 08:47**MOT test number** 554794558572**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Only just passed parking brake performance**Advice** Both front tyres are worn on the inner edge**MOT #4** 2015-08-14 11:49**MOT test number** 378746625440**Result** ✓ Passed**MOT #3** 2014-09-23 10:21**MOT test number** 988566264288**Result** ✓ Passed**MOT #2** 2013-03-21 10:22**MOT test number** 328830883087**Result** ✓ Passed**MOT #1** 2012-03-30 10:13**MOT test number** 955970592085**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
23 September 2022

X

MOT

Expired:
21 August 2023

| | |
|------------------|---------------------------------|
| Tax status | Expired at 23 September |
| Days left | 585 days too late |
| MOT expiry date | 21 August 2023 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 48 |
| Band | J |
| Single payment (12 months) | £ 365,00,- |
| Single six month payment | £ 200,75,- |
| Total payable by 12 monthly instalments | £ 383,25,- |



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | SD09VZJ |
| Plate since | 2024-03-29 |
| Current registration | SD09VZJ |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 15 |
| First mileage registration | 2009-04-12 |
| Last registration | 2022-08-11 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2009-04-12 | 17 mi |
| Registration #2 | 2012-03-30 | 10.971 mi |
| Registration #3 | 2013-03-21 | 14.575 mi |
| Registration #4 | 2014-09-23 | 20.694 mi |
| Registration #5 | 2015-08-14 | 24.612 mi |
| Registration #6 | 2016-08-15 | 28.865 mi |
| Registration #7 | 2017-08-11 | 32.115 mi |
| Registration #8 | 2017-08-22 | 32.195 mi |
| Registration #9 | 2018-08-22 | 35.277 mi |
| Registration #10 | 2019-08-22 | 38.359 mi |
| Registration #11 | 2020-08-22 | 41.441 mi |
| Registration #12 | 2021-08-22 | 44.523 mi |
| Registration #13 | 2022-08-22 | 47.605 mi |
| Registration #14 | 2023-08-22 | 50.687 mi |
| Registration #15 | 2024-08-22 | 53.769 mi |

More info >



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2012 mm |
| Height | 1296 mm |
| Length | 4103 mm |
| Wheel base | 2430 mm |
| Kerb weight | 1415 kg |
| Max. allowed weight | 1705 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of seats | 2 |
| Number of axles | 2 |
| Engine number | 27195431253706 |