





report date: 2024-03-29

### General information

Make	HONDA
Model	JAZZ I-VTEC EX
Colour	White
Year of manufacture	2017
Top speed	113 mph
0 - 60 mph	12.3 seconds
Gearbox	1 speed CVT

## Engine & fuel consumption

Power	101 BHP
Max. torque	123 Nm at 5.000 rpm
Engine capacity	1.318 сс
Cylinders	4
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	62.8 mpg
Consumption combined	57.7 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

# Internet history

## Entry 2

Date 2021-12-11

Pictures 45

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-01-31

Pictures 9

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2025-01-04
MOT pass rate	100 %
MOT passed	4
Failed MOT tests	0
Total advice items	11
Total items failed	0

MOT #4	2024-01-05 14:25
MOT test number	930373661455
Result	✓ Passed
Next expiry date	2025-01-04
Advice TPMS light on	
Advice Nearside Rear Inner Nail in tyre	

MOT #3		2022-12-27 11:39
MOT test	number	994836384273
Result		<b>✓</b> Passed
Advice	Nearside Rear Nail in tyre	
Advice	Tpms light displayed	

MOT #2	2021-12-09 13:10
MOT test number	639609772366
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #1 2020-11-12 15:10

**MOT test number** 819163374365

Result ✓ Passed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Nearside Rear Suspension component mounting prescribed area damaged but not considered excessive Door sill damaged. Rear arm PA (5.3.6 (a) (i)) Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	4 January 2025
Full MOT history	See MOT history

#### Tax calculation

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	
manus .	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	OK SIE
Flate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-11-16
Last registration	2024-01-05
Complete history	See info



Registration #1	2017-11-16	9 mi
Registration #2	2020-11-12	26.231 mi
Registration #3		11.777 es
Registration #4	2021-12-09	28.164 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



HV67VGN report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	93%
Children	85%
Pedestrian	73%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1694 mm
Height	1550 mm
Length	3995 mm
Wheel base	2530 mm
Kerb weight	1132 kg
Max. allowed weight	1605 kg

# Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	L13B21160060

CarCheck.co.uk page 11/11