





report date: 2024-03-28

General information

Make	BMW
Model	1 SERIES 118I M SPORT
Colour	Grey
Year of manufacture	2013
Top speed	140 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.9 mpg
CO2 emission	137 g/km
CO2 label	E



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date 2021-06-05

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-06-17
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	41
Total items failed	6

MOT #11		2023-06-17 20:10
MOT test	number	611286150394
Result		✓ Passed
Next expi	ry date	2024-06-17
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weak	ened (1.1.14 (a) (ii))
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weaker	ned (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weak	kened (1.1.14 (a) (ii))
Advice	Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Minor	Offside Windscreen wiper blade defective (3.4 (b) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #10 2023-06-17 20:10

MOT test number 505216028564

Result X Failed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification Nearside Headlamp aim too low (4.1.2 (a))

Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Offside Headlamp aim too low (4.1.2 (a))

Minor Offside Windscreen wiper blade defective (3.4 (b) (i))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9 2022-06-18 11:59

MOT test number 582652162276

Result

Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #8 2022-05-19 10:48

MOT test number 772564908499

Result X Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front daytime running light does not switch to side light when operated but light is

visble

Fail Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Play in steering rack inner joint(s)

Advice Run flat and non run flat mixed on rear axle

Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #7 2021-05-12 09:19

MOT test number 921085539226

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6 2020-05-19 14:50

MOT test number 680891740487

Result \rightarrow Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #5		2019-04-24 14:01
MOT test	number	236290053879
Result		✓ Passed
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #4		2018-04-09 11:50
MOT test	number	335458011680
Result		✓ Passed
MOT #3		2017-05-03 11:46
MOT test	number	202614873106
Result		✓ Passed
Advice	Under trays fitted obstructing some components	
Advice	Rear Tyre worn close to the legal limit both on 3mm (4.1.E.1)	
Advice	Nearside Rear Nail in tyre	

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #2 2017-05-01 10:25 **MOT** test number 840735794791 Result **★** Failed **Advice** Rear Tyre worn close to the legal limit both on 3mm (4.1.E.1) Offside Front Steering arm has relative movement at its fixings inner rack arm (2.2.B.1h) Fail Offside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b) Fail Advice Under trays fitted obstructing some components Advice Nearside Rear Nail in tyre Advice Coolant level below min

MOT #1

MOT test number

489351914138

Result

Advice Rear pads very low

CarCheck.co.uk page 7/14



Tax & MOT check



Expires: 17 June 2024



Expired at 1 February 2024

Days left 88 days too late

MOT expiry date 17 June 2024

Full MOT history See MOT history

Tax calculation

Tax status

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Daillage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report J	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	UK NES
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-05-02
Last registration	2023-06-17
Complete history	See info



Registration #1	2013-05-02	26 mi
Registration #1	2013-03-02	20 1111
Registration #2	2016-04-29	30.977 mi
Registration #3	2017-05-01	39.730 mi
Registration #4	2017-05-03	39.737 mi
Registration #5	2018-04-09	47.399 mi
Registration #6	2019-04-24	56.777 mi
Registration #7	2020-05-19	60.988 mi
Registration #8		11.177 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 ms
Registration #12		11.777 es
Registration #13		0.777 no

More info >

CarCheck.co.uk page 13/14




Car features

50225	Air conditionin
60295	
60482	
60501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1421 mm
Length	4324 mm
Wheel base	2690 mm
Kerb weight	1300 kg
Max. allowed weight	1865 kg

Additional information

Fuel tank capacity	52	
Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	5	page 14/14

Number of axles2Engine numberA172J594