



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 LX
Colour	Silver
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	111 Nm at 2.600 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-09
Pictures	49
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #29	2023-03-06 11:29
MOT test number	232119637352
Result	✓ Passed
Next expiry date	2024-03-10
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #28	2022-03-07 10:24
MOT test number	232688912881
Result	✓ Passed

MOT #27	2021-02-24 15:41
MOT test number	657628731427
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear light unit has slight water in it
Advice	Oil leak, but not excessive engine has slight oil seepage (8.4.1 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear wheel arch has slight damage
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #26**

2021-02-24 15:41

MOT test number

958578934592

Result**✗ Failed****Advice** Oil leak, but not excessive engine has slight oil seepage (8.4.1 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear light unit has slight water in it**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear wheel arch has slight damage**Pass with rectification** Offside Front Side repeater not working (4.4.1 (a) (ii))**MOT #25**

2020-02-14 10:00

MOT test number

835124422434

Result**✓ Passed****Advice** Offside Rear wheel arch has slight damage**Advice** Oil leak, but not excessive engine has slight oil seepage (8.4.1 (a) (i))**Advice** Offside Rear light unit slightly damp inside**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear brakes have slight imbalance



MOT #24	2019-02-28 17:03
MOT test number	947377653571
Result	✓ Passed

Advice	Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear mounting bush slightly un-bonding (5.3.4 (a) (i))
Advice	Slight imbalance of rear brakes
Advice	Throttle pedal anti slip missing
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Oil leak, but not excessive engine has slight oil seepage (8.4.1 (a) (i))
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Minor	Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis by axle mounts (5.3.6 (a) (i))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Exhaust emissions just pass on the limit
Advice	Offside Rear wheel arch slightly damaged
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Oil leak, but not excessive gearbox has slight oil seepage (8.4.1 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Inner wheel arch cover close to rubbing on tyre
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis by axle mounts (5.3.6 (a) (i))



MOT #23	2019-02-28 12:54
MOT test number	242546162219
Result	✗ Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis by axle mounts (5.3.6 (a) (i))

Minor Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Oil leak, but not excessive engine has slight oil seepage (8.4.1 (a) (i))

Pass with rectification Nearside Headlamp not working on main beam (4.1.1 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Throttle pedal anti slip missing

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Exhaust emissions just pass on the limit

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear mounting bush slightly un-bonding (5.3.4 (a) (i))

Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Offside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))

Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))

Advice Offside Rear wheel arch slightly damaged

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Oil leak, but not excessive gearbox has slight oil seepage (8.4.1 (a) (i))

Fail Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis by axle mounts (5.3.6 (a) (i))

Advice Nearside Rear Inner wheel arch cover close to rubbing on tyre

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Slight imbalance of rear brakes

**MOT #22**

2018-03-03 11:40

MOT test number

179687076506

Result

✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened corroded lip on edges (3.5.1i)
- Advice** Slight imbalance of front brakes
- Advice** Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)
- Advice** Offside Rear slight damage rear wheel arch
- Advice** Nearside Front Side repeater slightly discoloured (1.4.A.2f)
- Advice** Offside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Front coil spring corroded offside & nearside (2.4.C.1b)

MOT #21

2017-02-25 10:11

MOT test number

991250841977

Result

✓ Passed

- Advice** Slight engine oil seepage
- Advice** Tyre worn close to the legal limit offside front tyre inner edge (4.1.E.1)
- Advice** Coil spring corroded offside & nearside front (2.4.C.1b)
- Advice** Slight corrosion edge of front brake discs
- Advice** Offside Rear Lower Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Slight damage offside rear wing/ arch
- Advice** Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)



MOT #20

2017-02-25 10:11

MOT test number

631239878100

Result

✗ Failed

- Advice

Front Brake pad(s) wearing thin (3.5.1g)
- Advice

Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice

Slight damage offside rear wing/ arch
- Advice

Slight engine oil seepage
- Pass with rectification

Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice

Tyre worn close to the legal limit offside front tyre inner edge (4.1.E.1)
- Advice

Coil spring corroded offside & nearside front (2.4.C.1b)
- Advice

Offside Rear Lower Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice

Slight corrosion edge of front brake discs
- Pass with rectification

Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #192016-03-05 09:00

MOT test number355688392452

Result		✓ Passed
Advice	Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)	
Advice	Offside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)	
Advice	Nearside Front Tyre worn close to the legal limit edge of tyre (4.1.E.1)	
Advice	Slight damage offside rear wing/bumper	
Advice	Rear parking (secondary) brake grabbing slightly (3.7.B.6b)	
Advice	Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)	
Advice	Offside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)	
Advice	Brake disc worn, pitted or scored, but not seriously weakened front brake discs slightly corroded (3.5.1i)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	

**MOT #18**

2016-03-04 13:57

MOT test number

315013416695

Result**✗ Failed**

- Advice** Offside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Nearside Front Tyre worn close to the legal limit edge of tyre (4.1.E.1)
- Fail** Rear parking (secondary) brakes imbalanced (3.7.B.6b)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Advice** Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Slight damage offside rear wing/bumper
- Advice** Offside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Brake disc worn, pitted or scored, but not seriously weakened front brake discs slightly corroded (3.5.1i)
- Advice** Rear parking (secondary) brake grabbing slightly (3.7.B.6b)
- Fail** Exhaust system not adequately supported front support bracket cracked (7.1.1)
- Pass with rectification** Nearside Front Headlamp aim too low (1.8)

MOT #17

2015-02-21 12:05

MOT test number

167642255060

Result**✓ Passed**

- Advice** Nearside Front front brake fluctuating, but not excessively (3.7.B.3)
- Notice** Slight damage offside rear wing
- Advice** Offside Inner Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Advice** Nearside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #16**

2015-02-20 10:47

MOT test number

838031555053

Result**✗ Failed****Advice** Offside Inner Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Front coil spring corroded (2.4.C.1b)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Battery weak**Advice** Nearside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Rear fog lamp not working (1.3.2b)**Advice** Nearside Front front brake fluctuating, but not excessively (3.7.B.3)**Notice** Slight damage offside rear wing**Fail** Offside Front coil spring broken (2.4.C.1a)

**MOT #15**

2014-02-28 12:34

MOT test number

318239554079

Result

✓ Passed

- Notice** Fuel tank strap corroded
- Advice** Nearside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Notice** Exhaust emissions close to limit
- Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #14

2014-02-28 12:34

MOT test number

268709954068

Result

✗ Failed

- Notice** Fuel tank strap corroded
- Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)
- Pass with rectification** Offside Headlamp aim too high and too far to the left. (1.8)
- Advice** Nearside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Notice** Exhaust emissions close to limit
- Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Pass with rectification** Offside Front Side repeater incorrect colour (1.4.A.2f)

MOT #13

2013-03-11 09:45

MOT test number

608290373080

Result

✓ Passed

- Notice** Emissions only just met requirements
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Notice** Items removed from driver's view prior to test

**MOT #12** 2013-03-01 15:51**MOT test number** 745170163099**Result** ✗ Failed**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Fail** Rear fog lamp not working (1.3.2b)**MOT #11** 2012-02-23 14:42**MOT test number** 568104252087**Result** ✓ Passed**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #10** 2012-02-23 14:42**MOT test number** 656144452085**Result** ✗ Failed**Pass with rectification** Offside Steering rack insecure (2.2.B.1a)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Pass with rectification** Centre Rear fog lamp not working (1.3.2b)**MOT #9** 2011-05-09 17:04**MOT test number** 395939021182**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #8** 2011-05-09 17:04**MOT test number** 317229321150**Result** ✗ Failed**Pass with rectification** Offside Front All position lamps not working (1.1.A.3b)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #7** 2010-04-23 14:35**MOT test number** 541463010152**Result** ✓ Passed**MOT #6** 2009-03-28 10:50**MOT test number** 722397589084**Result** ✓ Passed**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #5** 2009-03-28 10:50**MOT test number** 403407689069**Result** ✗ Failed**Pass with rectification** Centre Rear fog lamp not working (1.3.2b)**Pass with rectification** Nearside Headlamp aim beam image kick up to the offside (1.8)**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)

**MOT #4** 2008-04-09 12:28**MOT test number** 210260908152**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2007-04-10 10:17**MOT test number** 233210507445**Result** ✓ Passed**MOT #2** 2007-04-10 10:17**MOT test number** 150330007164**Result** ✗ Failed**Pass with rectification** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Pass with rectification** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Pass with rectification** Nearside Front brake disc excessively scored (3.5.1h)**MOT #1** 2006-03-16 15:20**MOT test number** 880715976036**Result** ✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	CN53KXX
Plate since	2024-03-29
Current registration	CN53KXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2003-10-01
Last registration	2023-03-06
Complete history	See info



Registration #1	2003-10-01	14 mi
Registration #2	2006-03-16	34.644 mi
Registration #3	2007-04-10	43.230 mi
Registration #4	2008-04-09	51.223 mi
Registration #5	2009-03-28	60.250 mi
Registration #6	2010-04-23	70.402 mi
Registration #7	2011-05-09	77.826 mi
Registration #8	2012-02-23	80.818 mi
Registration #9	2013-03-01	86.787 mi
Registration #10	2013-03-11	86.795 mi
Registration #11	2014-02-28	100.736 mi
Registration #12	2015-02-20	113.143 mi
Registration #13	2015-02-21	113.147 mi
Registration #14	2016-03-01	113.147 mi
Registration #15	2016-03-01	113.147 mi
Registration #16	2016-03-01	113.147 mi
Registration #17	2016-03-01	113.147 mi
Registration #18	2016-03-01	113.147 mi
Registration #19	2016-03-01	113.147 mi
Registration #20	2016-03-01	113.147 mi
Registration #21	2016-03-01	113.147 mi
Registration #22	2016-03-01	113.147 mi
Registration #23	2016-03-01	113.147 mi
Registration #24	2016-03-01	113.147 mi
Registration #25	2016-03-01	113.147 mi
Registration #26	2016-03-01	113.147 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	950 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	FSJ44493145