



report date: 2024-03-28

General information

Make	FORD
Model	KA ZETEC CLIMATE
Colour	Black
Year of manufacture	-
Top speed	104 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	106 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	43.5 mpg



LABEL UNKNOWN

**MOT history****MOT #16**

2023-05-19 16:34

MOT test number

412940460053

Result**✗ Failed**

Fail Offside Front Suspension arm pin or bush excessively worn Rear bush centre bonding completely failed (5.3.4 (a) (i))

Advice Considerable corrosion front macpherson struts and hub assemblies

Advice Rear Sub-frame pin or bush worn but not resulting in excessive movement Both, axle beam bushes deteriorated with slight movement (5.3.4 (a) (i))

Advice Considerable corrosion top half of fuel tank

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Minor Offside Registration plate lamp insecure (4.7.1 (c) (i))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Front Suspension arm pin or bush excessively worn Rear bush centre bonding completely failed (5.3.4 (a) (i))

Advice Evident from under vehicle, rear end crash damage, boot floor distorted

Fail Offside Rear Subframe mounting prescribed area excessively corroded significantly reducing structural strength Inner sill (5.3.6 (a) (i))

Advice Body damage nearside door and 3/4 panel

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #15

2022-05-23 10:26

MOT test number

393604838389

Result**✓ Passed**

Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #14** 2021-05-25 08:39**MOT test number** 446759764198**Result** ✓ Passed**MOT #13** 2021-05-24 09:09**MOT test number** 549822505185**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting near suspension mount (6.2.2 (d) (i))**MOT #12** 2020-07-28 08:27**MOT test number** 375591704971**Result** ✓ Passed**Advice** Under side of vehicle corroded in various places**Advice** Both front lower arm bushes perished**MOT #11** 2019-07-15 11:02**MOT test number** 203332993378**Result** ✓ Passed**MOT #10** 2018-07-17 10:34**MOT test number** 984945433474**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened BOTH (1.1.14 (a) (ii))**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Tyre slightly damaged/cracking or perishing BOTH (5.2.3 (d) (i))

**MOT #9** 2017-07-18 09:14**MOT test number** 107740997190**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened BOTH (3.5.1i)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** ALL FOUR TYRES SMALL CRACKS IN TREAD

MOT #8 2016-07-20 12:04**MOT test number** 583115641734**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #7 2015-07-21 10:40**MOT test number** 277162805259**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6 2014-07-21 15:01**MOT test number** 949132104252**Result** ✓ Passed**MOT #5** 2014-07-21 10:48**MOT test number** 149092204270**Result** ✗ Failed

- Fail** Nearside Front coil spring broken (2.4.C.1a)



MOT #4	2013-07-01 15:29
---------------	------------------

MOT test number	738852083116
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2012-07-24 10:10
---------------	------------------

MOT test number	526766402288
------------------------	--------------

Result	✓ Passed
---------------	----------

- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #2	2011-07-04 10:53
---------------	------------------

MOT test number	178485081105
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2010-07-20 12:27
---------------	------------------

MOT test number	302681500461
------------------------	--------------

Result	✓ Passed
---------------	----------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	KX07ELZ
Plate since	2019-03-28
Current registration	KX07ELZ
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-07-27
Last registration	2023-05-19
Complete history	See info



Registration #1	2007-07-27	7 mi
Registration #2	2010-07-20	6.518 mi
Registration #3	2011-07-04	7.852 mi
Registration #4	2012-07-24	10.704 mi
Registration #5	2013-07-01	13.391 mi
Registration #6	2014-07-21	14.145 mi
Registration #7	2014-07-21	14.145 mi
Registration #8	2015-07-21	14.743 mi
Registration #9	2016-07-20	15.913 mi
Registration #10	2017-05-20	16.277 mi
Registration #11	2017-05-20	16.277 mi
Registration #12	2017-05-20	16.277 mi
Registration #13	2017-05-20	16.277 mi
Registration #14	2017-05-20	16.277 mi
Registration #15	2017-05-20	16.277 mi
Registration #16	2017-05-20	16.277 mi
Registration #17	2017-05-20	16.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1827 mm
Height	1413 mm
Length	3620 mm
Wheel base	2448 mm
Max. allowed weight	1265 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2

Engine number

7Y04329