



HYUNDAI

EF6IBVW

report date: 2024-03-29

General information

Make	HYUNDAI
Model	I30 COMFORT
Colour	White
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	137 Nm at 5.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg



LABEL UNKNOWN

**MOT history**

<b>MOT #12</b>	2021-12-03 11:09
<b>MOT test number</b>	331040627196
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-12-03

<b>MOT #11</b>	2021-11-29 15:25
<b>MOT test number</b>	159600820614
<b>Result</b>	✗ Failed

- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Front Windscreen wiper missing (3.4 (a))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Offside Rear Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))
- Fail** Nearside Front Headlamp lens seriously defective (4.1.1 (b) (ii))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

<b>MOT #10</b>	2020-12-02 16:40
<b>MOT test number</b>	780245669188
<b>Result</b>	✓ Passed

- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Minor** Offside Front Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))

**MOT #9** 2019-06-04 09:53**MOT test number** 224564594975**Result** ✓ Passed**Advice** Park brake has little reserve travel**MOT #8** 2018-06-01 13:58**MOT test number** 870213026812**Result** ✓ Passed**Advice** Offside Rear Parking (secondary brake) grabbing slightly (1.3.1 (c))**MOT #7** 2018-06-01 13:58**MOT test number** 553405141165**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Parking (secondary brake) grabbing slightly (1.3.1 (c))**MOT #6** 2017-05-17 16:26**MOT test number** 964026788772**Result** ✓ Passed**MOT #5** 2017-05-17 04:30**MOT test number** 905935270622**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

**MOT #4** 2016-05-11 11:42**MOT test number** 430820463578**Result** ✓ Passed

**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output damp (1.7.5a)

**MOT #3** 2016-05-11 09:22**MOT test number** 114718499594**Result** ✗ Failed

**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output damp (1.7.5a)

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #2** 2015-05-05 12:46**MOT test number** 357645325127**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #1** 2015-05-05 09:41**MOT test number** 236155425144**Result** ✗ Failed

**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Fail** Offside Stop lamp not working (1.2.1b)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-12-01
Last registration	2021-12-03
Complete history	<a href="#">See info</a>



Registration #1	2011-12-01	9 mi
Registration #2	2015-05-05	35.861 mi
Registration #3	2015-05-05	35.861 mi
Registration #4	2016-05-11	42.200 mi
Registration #5	2016-05-11	42.200 mi
Registration #6	2017-05-17	45.483 mi
Registration #7	2017-05-17	45.483 mi
Registration #8	2017-05-17	45.483 mi
Registration #9	2017-05-17	45.483 mi
Registration #10	2017-05-17	45.483 mi
Registration #11	2017-05-17	45.483 mi
Registration #12	2017-05-17	45.483 mi
Registration #13	2017-05-17	45.483 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1775 mm
Height	1480 mm
Length	4280 mm
Wheel base	2650 mm
Kerb weight	1293 kg
Max. allowed weight	1720 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	G4FABZ349089
---------------	--------------