



report date: 2024-03-28

General information

Make	AUDI
Model	A3 TDI SPORT
Colour	White
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 2.500 rpm
Engine capacity	1.595 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





MOT history

MOT expiry date	2024-10-25
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	35
Total items failed	6

MOT #16	2023-10-20 10:37
MOT test number	113980363721
Result	✓ Passed
Next expiry date	2024-10-25
Advice	Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front to rear brake pipes covered in underneath

**MOT #15**

2023-10-19 07:55

**MOT test number**

407884607280

**Result****✗ Failed**

- Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Front to rear brake pipes covered in underneath
- MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))
- DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #14**

2022-10-25 09:17

**MOT test number**

983312015574

**Result****✓ Passed**

- Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2021-10-14 16:41

**MOT test number**

544027140366

**Result****✓ Passed**

**MOT #12** 2020-10-26 13:56**MOT test number** 383343765961**Result** ✓ Passed**MOT #11** 2019-08-21 12:14**MOT test number** 343502615311**Result** ✓ Passed**MOT #10** 2018-09-10 15:24**MOT test number** 588042792579**Result** ✓ Passed**MOT #9** 2018-09-10 10:47**MOT test number** 104585941966**Result** ✗ Failed**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #8** 2017-06-09 10:18**MOT test number** 468041565863**Result** ✓ Passed**MOT #7** 2016-07-20 14:59**MOT test number** 267562021474**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**MOT #6**

2016-07-06 15:57

**MOT test number**

669641040893

**Result****✗ Failed**

- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Centre exhaust clamp corroded and securing band broken
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front front brake fluctuating, but not excessively (3.7.B.3)
- Advice** Offside Rear nail in tyre
- Fail** Offside Rear rear brake binding (3.7.B.1)

**MOT #5**

2015-06-11 11:58

**MOT test number**

996372365101

**Result****✓ Passed**

- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Notice** Rear pads unevenly worn, nearside rear lower
- Notice** Offside front tyre worn on the inner edge of tyre tread

**MOT #4** 2015-06-11 10:30**MOT test number** 945002565165**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Offside front tyre worn on the inner edge of tyre tread**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Rear pads unevenly worn, nearside rear lower**MOT #3** 2014-06-14 10:24**MOT test number** 727515264179**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-06-04 16:29**MOT test number** 285875053427**Result** ✓ Passed**MOT #1** 2013-06-04 10:55**MOT test number** 816965353152**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2024

✓  
**MOT**  
**Expires:**  
25 October 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	2
<b>MOT expiry date</b>	25 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-




Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	<b>SH10XSR</b>
Plate since	2019-09-28
Current registration	<b>SH10XSR</b>
Plate since	2019-09-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-06-08
Last registration	2023-10-20
Complete history	<a href="#">See info</a>



Registration #1	2010-06-08	16 mi
Registration #2	2013-06-04	27.525 mi
Registration #3	2013-06-04	27.528 mi
Registration #4	2014-06-14	32.576 mi
Registration #5	2015-06-11	36.656 mi
Registration #6	2015-06-11	36.656 mi
Registration #7	2016-07-06	40.793 mi
Registration #8	2016-07-20	40.803 mi
Registration #9	2017-06-09	47.573 mi
Registration #10	2019-06-09	55.577 mi
Registration #11	2019-06-09	55.577 mi
Registration #12	2019-06-09	55.577 mi
Registration #13	2019-06-09	55.577 mi
Registration #14	2019-06-09	55.577 mi
Registration #15	2019-06-09	55.577 mi
Registration #16	2019-06-09	55.577 mi
Registration #17	2019-06-09	55.577 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1765 mm
Height	1424 mm
Length	4238 mm
Wheel base	2578 mm
Kerb weight	1430 kg
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	CAY 633036