



report date: 2024-03-29

General information

Make	KIA
Model	RIO 2
Colour	Blue
Year of manufacture	2011
Top speed	104 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	96 BHP
Max. torque	125 Nm at 4.700 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	40.4 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-05-26
Pictures	0
Listing price	View report

source: autoonline.co.uk

**MOT history**

MOT expiry date	2025-04-16
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	30
Total items failed	6

MOT #16 2024-04-17 10:30**MOT test number** 791577300238**Result** Passed**Next expiry date** 2025-04-16

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear axle corroded
- Advice** Front Suspension component corroded but not seriously weakened all components (5.3.3 (b) (i))

MOT #15 2023-05-03 13:44**MOT test number** 477632084315**Result** Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Oil leak, but not excessive from sump (8.4.1 (a) (i))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Rear Coil spring corroded n/s and o/s (5.3.1 (b) (i))
- Advice** Rear axle corroded

**MOT #14**

2022-05-19 10:03

MOT test number

119353692595

Result

✓ Passed

Minor Offside Front Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #13**

2021-05-24 16:12

MOT test number

986964413527

Result

✓ Passed

MOT #12

2021-05-24 10:16

MOT test number

114082110651

Result

✗ Failed

Fail Brake disc significantly and obviously worn both front discs (1.1.14 (a) (i))**Fail** Offside Front Suspension arm pin or bush excessively worn front wishbone bush (5.3.4 (a) (i))**Fail** Front Brakes imbalanced across an axle (1.2.1 (b) (i))**MOT #11**

2020-08-19 10:21

MOT test number

875734266420

Result

✓ Passed

Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10** 2019-06-21 11:24**MOT test number** 594954001906**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #9** 2019-06-21 11:24**MOT test number** 646833903370**Result** ✗ Failed**Minor** Offside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Pass with rectification** Exhaust system insecure Centre. (6.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2018-06-18 12:53**MOT test number** 546230189372**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))**Advice** Central Exhaust mounting defective (6.1.2 (a))**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Power steering component has slight seepage from a component steering rack (2.1.5 (a))

**MOT #7** 2018-06-18 11:44**MOT test number** 461404686953**Result** ✗ Failed**Advice** Offside Power steering component has slight seepage from a component steering rack (2.1.5 (a))**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Windscreen washer not working both (3.5 (a))**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))**Advice** Central Exhaust mounting defective (6.1.2 (a))**MOT #6** 2017-06-28 10:37**MOT test number** 888556322557**Result** ✓ Passed**Advice** Centre exhaust bracket snapped**MOT #5** 2016-06-17 10:47**MOT test number** 471926149641**Result** ✓ Passed**MOT #4** 2015-06-29 10:18**MOT test number** 315640585162**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2014-07-10 16:42**MOT test number** 469121094165**Result** ✓ Passed



MOT #2	2014-06-02 09:28
MOT test number	599983454134
Result	✓ Passed

MOT #1	2014-06-02 08:58
MOT test number	265653554195
Result	✗ Failed

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
16 April 2025

Tax status	Valid until 1 May
Days left	367
MOT expiry date	16 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	MT11GHB
Plate since	2019-03-29
Current registration	MT11GHB
Plate since	2019-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-07-01
Last registration	2024-04-17
Complete history	See info



Registration #1	2011-07-01	17 mi
Registration #2	2014-06-02	13.882 mi
Registration #3	2014-06-02	13.882 mi
Registration #4	2014-07-10	14.642 mi
Registration #5	2015-06-29	19.903 mi
Registration #6	2016-06-17	25.072 mi
Registration #7	2017-06-28	30.462 mi
Registration #8	2018-06-18	35.045 mi
Registration #9	2018-06-18	35.046 mi
Registration #10	2019-06-18	35.047 mi
Registration #11	2019-06-18	35.047 mi
Registration #12	2019-06-18	35.047 mi
Registration #13	2019-06-18	35.047 mi
Registration #14	2019-06-18	35.047 mi
Registration #15	2019-06-18	35.047 mi
Registration #16	2019-06-18	35.047 mi
Registration #17	2019-06-18	35.047 mi
Registration #18	2019-06-18	35.047 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1695 mm
Height	1470 mm
Length	3990 mm
Wheel base	2500 mm
Kerb weight	1266 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4EEAH412695