



report date: 2024-03-28

General information

Make	SUZUKI
Model	SX4 SZ5
Colour	Silver
Year of manufacture	2011
Top speed	109 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	145 Nm at 4.400 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-08-10
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	30
Total items failed	5

MOT #152023-08-11 13:53

MOT test number377634169918

Result✔ Passed

Next expiry date2024-08-10

- AdviceOffside Rear Coil spring corroded (5.3.1 (b) (i))
- AdviceNearside Front shock corroded
- AdviceRear Brake disc worn, but not excessively (1.1.14 (a) (i))
- AdviceNearside Rear shock corroded
- AdviceNearside Front Coil spring corroded (5.3.1 (b) (i))
- AdviceFront subframe corroded
- AdviceNearside Rear Coil spring corroded (5.3.1 (b) (i))
- AdviceGeneral corrosion to chassis
- AdviceFront Brake disc worn, but not excessively (1.1.14 (a) (i))
- AdviceOffside Front shock corroded
- AdviceOffside Rear shock corroded
- AdviceOffside Front Coil spring corroded (5.3.1 (b) (i))
- AdviceRear subframe corroded

**MOT #14**

2022-09-06 08:56

MOT test number

241793220518

Result

✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Offside Rear Oil leak, but not excessive diff (8.4.1 (a) (i))

MOT #13

2021-09-08 14:51

MOT test number

264328292600

Result

✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Front Nail in tyre

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #12

2020-08-28 08:43

MOT test number

224191920798

Result

✓ Passed

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #11** 2019-09-12 09:19**MOT test number** 710372657046**Result** ✓ Passed**Advice** Offside Suspension arm pin or bush worn but not resulting in excessive movement rear bush coming away (5.3.4 (a) (i))**Advice** Offside Rear Valve stem slightly damaged starting to crack (5.2.3 (j))**Advice** Nearside Suspension arm pin or bush worn but not resulting in excessive movement rear bush coming away (5.3.4 (a) (i))**Advice** Nearside Rear Valve stem slightly damaged starting to crack (5.2.3 (j))**MOT #10** 2018-09-11 15:01**MOT test number** 345217981716**Result** ✓ Passed**MOT #9** 2018-09-10 13:44**MOT test number** 300539592769**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #8** 2017-09-13 15:03**MOT test number** 691227121254**Result** ✓ Passed**MOT #7** 2017-01-19 14:48**MOT test number** 934975374555**Result** ✓ Passed**MOT #6** 2017-01-18 09:26**MOT test number** 146408985434**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)

**MOT #5** 2016-01-26 10:09**MOT test number** 934997138713**Result** ✓ Passed**MOT #4** 2016-01-22 14:35**MOT test number** 841397644417**Result** ✗ Failed**Fail** Nearside Headlamp aim too low (1.8)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #3** 2015-01-22 08:59**MOT test number** 169842725046**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2014-01-17 09:26**MOT test number** 109137014491**Result** ✓ Passed**MOT #1** 2014-01-17 09:26**MOT test number** 897787014010**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
10 August 2024

Tax status	Valid until 1 April
Days left	338
MOT expiry date	10 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-01-11
Last registration	2023-08-11
Complete history	See info



Registration #1	2011-01-11	13 mi
Registration #2	2014-01-17	15.568 mi
Registration #3	2015-01-22	20.587 mi
Registration #4	2016-01-22	25.021 mi
Registration #5	2016-01-26	25.021 mi
Registration #6	2017-01-18	30.123 mi
Registration #7	2017-01-19	30.123 mi
Registration #8	2017-09-13	33.386 mi
Registration #9	2018-01-22	35.377 mi
Registration #10	2018-01-22	35.377 mi
Registration #11	2018-01-22	35.377 mi
Registration #12	2018-01-22	35.377 mi
Registration #13	2018-01-22	35.377 mi
Registration #14	2018-01-22	35.377 mi
Registration #15	2018-01-22	35.377 mi
Registration #16	2018-01-22	35.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1730 mm
Height	1570 mm
Length	4120 mm
Wheel base	2500 mm
Kerb weight	1200 kg
Max. allowed weight	1685 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-1618174