



report date: 2024-03-29

General information

Make	FIAT
Model	GRANDE PUNTO SOUND
Colour	Black
Year of manufacture	2010
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-24
Pictures	16
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-11
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	16
Total items failed	20

MOT #18	2023-07-12 14:38
MOT test number	674965765656
Result	✓ Passed
Next expiry date	2024-07-11
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Minor	Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #17**

2023-07-04 08:50

MOT test number

727444775199

Result**✗ Failed****Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**Fail** Offside Rear Direction indicator not working (4.4.1 (a) (ii))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #16**

2022-06-29 14:13

MOT test number

843608730197

Result**✓ Passed****Advice** Rear Both tyres starting to crack due to age**MOT #15**

2022-06-25 09:17

MOT test number

686406481605

Result**✗ Failed****Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Fail** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))**Advice** Rear Both tyres starting to crack due to age**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Oil leaking excessively from transmission Poss nearside driveshaft oil seal (8.4.1 (a) (i))

**MOT #14** 2021-06-25 13:43**MOT test number** 326719664468**Result** ✓ Passed**MOT #13** 2021-05-12 14:17**MOT test number** 946380484404**Result** ✗ Failed

- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Sub-frame attachment bracket/mounting missing (5.3.3 (a) (ii))
- Fail** Offside Rear Shock absorbers has negligible damping effect (5.3.2 (d))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Tyre tread depth below requirements of 1.6mm Both front (5.2.3 (e))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #12 2020-09-28 11:18**MOT test number** 442613322281**Result** ✓ Passed**MOT #11** 2020-09-28 09:02**MOT test number** 261320399629**Result** ✗ Failed

- Fail** Nearside Front Sub-frame attachment bracket/mounting insecure (5.3.3 (a) (i))

MOT #10 2019-09-11 09:53**MOT test number** 507635585051**Result** ✓ Passed

**MOT #9** 2018-09-27 10:09**MOT test number** 738651519173**Result** ✓ Passed**MOT #8** 2018-09-27 08:19**MOT test number** 511535965859**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively blade split (3.4 (b) (ii))**Fail** Offside Windscreen wiper does not clear the windscreen effectively blade split (3.4 (b) (ii))**Advice** Both rear tyres sidewalls perished**MOT #7** 2017-09-15 12:50**MOT test number** 548636828844**Result** ✓ Passed**Advice** All four tires deteriorated change as soon as possible**Advice** Offside Front wiper deteriorated**MOT #6** 2016-08-19 08:28**MOT test number** 411880346160**Result** ✓ Passed**Advice** Rear both tyre sidewalls deteriorated**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2015-07-08 08:28**MOT test number** 659139085178**Result** ✓ Passed

**MOT #4** 2015-07-04 08:40**MOT test number** 489895885101**Result** ✗ Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #3 2014-12-19 14:34**MOT test number** 618073154304**Result** ✓ Passed**MOT #2** 2014-12-16 11:46**MOT test number** 796520954393**Result** ✗ Failed

Fail Nearside Headlamp insecure (1.7.3)

Fail Nearside Headlamp aim too low (1.8)

MOT #1 2013-12-04 11:38**MOT test number** 649678733335**Result** ✓ Passed

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
11 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	11 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-12-24
Last registration	2023-07-12
Complete history	See info



Registration #1	2010-12-24	8 mi
Registration #2	2013-12-04	13.642 mi
Registration #3	2014-12-16	18.024 mi
Registration #4	2014-12-19	18.234 mi
Registration #5	2015-07-04	19.792 mi
Registration #6	2015-07-08	19.793 mi
Registration #7	2016-08-19	28.045 mi
Registration #8	2017-09-15	36.078 mi
Registration #9	2018-09-27	42.872 mi
Registration #10	2018-09-27	42.872 mi
Registration #11	2019-05-29	51.377 mi
Registration #12	2019-05-29	51.377 mi
Registration #13	2019-05-29	51.377 mi
Registration #14	2019-05-29	51.377 mi
Registration #15	2019-05-29	51.377 mi
Registration #16	2019-05-29	51.377 mi
Registration #17	2019-05-29	51.377 mi
Registration #18	2019-05-29	51.377 mi
Registration #19	2019-05-29	51.377 mi
Registration #20	2019-05-29	51.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	9632561
---------------	---------