



TOYOTA

YAO2KJG

report date: 2024-03-29

General information

Make	TOYOTA
Model	HILUX 270 4WD EX D/C MWB P/U
Colour	Silver
Year of manufacture	2002
Gearbox	5 speed Manual

Engine & fuel consumption

Power	999 BHP
Max. torque	9999 Nm at 9.999 rpm
Engine capacity	2.494 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-05
Pictures	37
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-08-17
MOT pass rate	64 %
MOT passed	16
Failed MOT tests	9
Total advice items	61
Total items failed	27

MOT #25	2021-07-19 11:13
MOT test number	112587928928
Result	✓ Passed
Next expiry date	2022-07-29
Advice	Rear Exhaust has a minor leak of exhaust gases Silencer (6.1.2 (a))

MOT #24	2020-07-30 09:05
MOT test number	206519507993
Result	✓ Passed
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #23	2020-07-21 15:30
MOT test number	170313629116
Result	✗ Failed
Fail	Nearside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail	Nearside Front Service brake excessively binding (1.2.1 (f))
Fail	Offside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #22** 2019-07-31 13:06**MOT test number** 382249476098**Result** ✓ Passed**Advice** Offside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Brake pipe corroded, covered in grease or other material All (1.1.11 (c))**MOT #21** 2018-07-26 10:17**MOT test number** 640996313043**Result** ✓ Passed**MOT #20** 2017-07-27 10:34**MOT test number** 656073973707**Result** ✓ Passed**Advice** Central Brake pipe slightly corroded (3.6.B.2c)**MOT #19** 2016-07-29 12:52**MOT test number** 311258183233**Result** ✓ Passed**Advice** Both rear tail lamps slightly damaged but not emitting a white light**Advice** Nearside Rear tyre slightly cracked**MOT #18** 2015-07-29 10:17**MOT test number** 799370415252**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #17	2015-07-28 12:13
MOT test number	558919905276
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
Fail	Nearside Rear Body has a sharp edge caused by corrosion (6.1.C.1)
Advice	Offside Front wheel bearing has slight play (2.5.A.3c)
Fail	Rear fog lamp not working (1.3.2b)
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail	Offside rear parking brake recording little or no effort (3.7.B.6a)

MOT #16	2014-08-01 13:49
MOT test number	395033314430
Result	✓ Passed
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)

**MOT #15**

2014-07-29 13:21

**MOT test number**

346490414245

**Result****✗ Failed**

- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Fail** Offside Rear reflector excessively damaged so that its function is impaired (1.5.1c)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Brakes imbalanced across an axle (3.7.B.5b)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Fail** Offside Rear rear brake recording little or no effort (3.7.B.5a)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)

**MOT #14**

2013-07-08 14:33

**MOT test number**

606089183131

**Result****✓ Passed**

- Advice** Offside Rear Leaf spring has slight side play at eye (shackle) (2.4.B.4)
- Notice** EML on
- Advice** Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Offside Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Leaf spring has slight side play at eye (shackle) (2.4.B.4)
- Notice** Items removed from driver's view prior to test
- Advice** Nearside Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #13**

2013-07-08 09:18

**MOT test number**

937059683112

**Result****✗ Failed**

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Nearside Rear Leaf spring has slight side play at eye (shackle) (2.4.B.4)
- Fail** Rear Rear fog lamp not working (1.3.2b)
- Notice** EML on
- Advice** Nearside Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Offside Rear Leaf spring has slight side play at eye (shackle) (2.4.B.4)
- Advice** Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Notice** Items removed from driver's view prior to test
- Advice** Offside Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #12**

2012-07-26 13:49

**MOT test number**

315528102447

**Result****✓ Passed**

- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Engine check light on
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #11**

2012-07-26 13:00

**MOT test number**

128168102249

**Result****✗ Failed****Fail** Front registration plate deteriorated (6.3.1d)**Notice** Engine check light on**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #10**

2011-07-27 14:24

**MOT test number**

265148301200

**Result****✓ Passed****Advice** Nearside Front Shock absorber has a slightly reduced damping effect (2.7.5)**Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Notice** Front bumper damaged.**Advice** Offside Front Shock absorber has a slightly reduced damping effect (2.7.5)**MOT #9**

2011-07-27 13:08

**MOT test number**

526958301238

**Result****✗ Failed****Advice** Offside Front Shock absorber has a slightly reduced damping effect (2.7.5)**Notice** Front bumper damaged.**Advice** Nearside Front Shock absorber has a slightly reduced damping effect (2.7.5)**Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Fail** Offside Outer Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)



**MOT #8** 2010-07-29 14:58**MOT test number** 191510210275**Result** ✓ Passed**Advice** Nearside Rear reflector slightly damaged but function not impaired (1.5.1c)**MOT #7** 2010-07-28 11:21**MOT test number** 722279100202**Result** ✗ Failed**Fail** Offside Outer Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)**Fail** Nearside Outer Front constant velocity joint gaiter split (2.5.C.1a)**Advice** Nearside Rear reflector slightly damaged but function not impaired (1.5.1c)**MOT #6** 2009-08-01 09:23**MOT test number** 923253619257**Result** ✓ Passed**Advice** Nearside Lower Ball joint has slight play (2.2.B.1f)**Advice** Nearside Ball joint has slight play (2.2.B.1f)**Notice** N/s rear lamp lens damaged but not showing a white light to rear**MOT #5** 2009-07-30 15:07**MOT test number** 883221319285**Result** ✗ Failed**Fail** Offside Front constant velocity joint gaiter split (2.5.C.1a)**Advice** Nearside Lower Ball joint has slight play (2.2.B.1f)**Notice** N/s rear lamp lens damaged but not showing a white light to rear**Fail** Nearside Front constant velocity joint gaiter split (2.5.C.1a)**Advice** Nearside Ball joint has slight play (2.2.B.1f)

**MOT #4** 2008-07-23 17:11**MOT test number** 663265708272**Result** ✓ Passed**MOT #3** 2007-08-01 14:21**MOT test number** 493613217262**Result** ✓ Passed**Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #2** 2007-08-01 14:21**MOT test number** 222773817276**Result** ✗ Failed**Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Pass with rectification** Offside Rear Brake lever has restricted free movement (3.5.1k)**Pass with rectification** Offside Front Windscreen wiper blade insecure (8.2.2)**MOT #1** 2006-07-29 11:09**MOT test number** 122010416241**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 August 2024

✓  
**MOT**

**Expires:**  
17 August 2024

**Tax status**

Valid until 1 August

**Days left**

93

**MOT expiry date**

17 August 2024

**Full MOT history**

[See MOT history](#)



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2002-08-09
Last registration	2021-07-19
Complete history	<a href="#">See info</a>



Registration #1	2002-08-09	25 mi
Registration #2	2006-07-29	24.233 mi
Registration #3	2007-08-01	31.877 mi
Registration #4	2008-07-23	40.063 mi
Registration #5	2009-07-30	45.857 mi
Registration #6	2009-08-01	45.861 mi
Registration #7	2010-07-28	52.655 mi
Registration #8	2010-07-29	52.655 mi
Registration #9	2011-07-27	57.886 mi
Registration #10	2011-07-27	57.886 mi
Registration #11	2012-07-26	63.059 mi
Registration #12	2012-07-26	63.059 mi
Registration #13	2013-07-08	68.048 mi
Registration #14	2013-07-08	68.048 mi
Registration #15	2013-07-08	68.048 mi
Registration #16	2013-07-08	68.048 mi
Registration #17	2013-07-08	68.048 mi
Registration #18	2013-07-08	68.048 mi
Registration #19	2013-07-08	68.048 mi
Registration #20	2013-07-08	68.048 mi
Registration #21	2013-07-08	68.048 mi
Registration #22	2013-07-08	68.048 mi
Registration #23	2013-07-08	68.048 mi
Registration #24	2013-07-08	68.048 mi
Registration #25	2013-07-08	68.048 mi
Registration #26	2013-07-08	68.048 mi



**More info** >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1465 mm
Height	1785 mm
Length	4785 mm
Kerb weight	1715 kg
Max. allowed weight	2780 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of seats	6
Number of axles	2
Engine number	2KD0953604