





General information

Make	ΤΟΥΟΤΑ
Model	AVENSIS VALVEMATIC TR
Colour	Black
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	180 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg
CO2 emission	155 g/km
CO2 label	G





Internet history

Entry 1	
Date	2021-07-11
Pictures	25
Listing price	View report

ULEZ



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-01
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	23
Total items failed	5

MOT #14	2023-07-24 14:47
MOT test number	908847704728
Result	✓ Passed
Next expiry date	2024-08-01

MOT #13		2023-07-24 11:15
MOT test numbe	er	150433147646
Result		🗙 Failed
DANGEROUS	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
DANGEROUS	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #12	2022-07-29 11:19
MOT test number	825244259517
Result	✓ Passed
MOT #11	2021-08-02 13.53

	2021-00-02 13.33
MOT test number	857641291245
Result	✓ Passed

MOT #10	2020-11-04 15:48
MOT test number	224937754937
Result	✓ Passed



MOT #9		2019-05-14 10:30
MOT test	number	484456500868
Result		✓ Passed
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Advice Nearside Front Tyre worn close to legal limit/worn on edge inner + outer edges (5.2.3 (e))	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Items removed from driver's view prior to test	

MOT #8	2018-05-15 10:28
MOT test number	882064598749
Result	✓ Passed

MOT #7		2017-05-16 09:04
MOT test	number	318761222624
Result		✓ Passed
Advice	Offside Front Headlamp has a product on the lens but not seriously reducir	ng light output (1.7.5a)
Advice	Under-trays fitted, obscuring some comopnents	
Advice (1.7.5a)	Nearside Front Headlamp has a product on the lens but not seriously reduce	cing light output

MOT #6	2016-05-20 14:47
MOT test number	238587352863
Result	✓ Passed



RO10NYB
report date: 2024-03-28

MOT #5	2016-05-17 14:58	
MOT test number	280693751656	
Result	🗙 Failed	
Fail Nearside Headlamp excessively damaged so that the light output is severely reduc	ed (1.7.5a)	
Fail Offside Headlamp aim too low and too far to the right. (1.8)		
Fail Nearside Headlamp insecure (1.7.3)		
Advice Damage to nearside front wing		
Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)		
Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)		

МОТ #4	2015-05-21 13:56
MOT test number	955311845137
Result	✓ Passed

MOT #3		2014-04-23 13:49
MOT test	number	258633614194
Result		✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advice	Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Notice	Offside front wiper blade deteriorating	

MOT #2		2013-04-08 16:27
MOT test	number	297978793067
Result		✓ Passed
Notice	Engine coolant below minimum mark.	
Notice	Engine covers fitted obscuring some components in the engine bay	



MOT #1		2013-04-06 10:49
MOT test	number	195896693026
Result		🗙 Failed
Notice	Engine coolant below minimum mark.	
Advice	Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Advice Front Brake pad(s) wearing thin (3.5.1g)	
Notice Engine covers fitted obscuring some components in the engine bay		
Fail Brakes imbalanced across an axle (3.7.B.5b)		
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3	s.5.1i)



Tax & MOT check

Tax due: 1 February 2025	✓ Taxed	Expires: 1 August 2024	✓ МОТ
Tax status			Valid until 1 February
Days left			278
MOT expiry date			1 August 2024
Full MOT history			See MOT history
Tax calculation			

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E E H - S - A
Date	*
Category	AMP.
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.


Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-04-23
Last registration	2023-07-24
Complete history	See info



Registration #1	2010-04-23	13 mi
Registration #2	2013-04-06	43.556 mi
Registration #3	2013-04-08	43.556 mi
Registration #4	2014-04-23	69.457 mi
Registration #5	2015-05-21	93.067 mi
Registration #6	2016-05-17	99.817 mi
Registration #7	2016-05-20	99.829 mi
Registration #8	2017-05-16	108.074 mi
Registration #9		11.227 mi
Registration #9 Registration #10		10.000 est
-		01.000 est 01.000 est 01.000 est
Registration #10		01.000 est 01.000 est 01.000 est 01.000 est
Registration #10 Registration #11		01.000 est 0.000 est 01.000 est 01.000 est 01.000 est
Registration #10 Registration #11 Registration #12		00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #10 Registration #11 Registration #12 Registration #13		00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	86%
Pedestrian	53%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight	
Width	1810 mm
Height	1480 mm
Length	4765 mm
Wheel base	2700 mm
Kerb weight	1510 kg
Max. allowed weight	2000 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5

5

Number of axles	2
Engine number	2ZFU265895