





report date: 2024-03-29

General information

Make	HYUNDAI
Model	ACCENT ATLANTIC LIMITED EDITION
Colour	Silver
Year of manufacture	2007
Top speed	104 mph
0 - 60 mph	14.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	96 BHP
Max. torque	125 Nm at 4.700 rpm
Engine capacity	1.399 сс
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	165 g/km
CO2 label	G



CarCheck.co.uk page 1/13



Internet history

Entry 1


Date 2021-10-25

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-12-04
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	19
Total items failed	3

MOT #16	2023-12-05 11:54
MOT test number	290821139799
Result	✓ Passed
Next expiry date	2024-12-04

MOT #15		2022-11-16 11:41
MOT test	number	361944065938
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/13



GL07NBJ

report date: 2024-03-29

MOT #14 2022-11-09 10:55

MOT test number 904752383254

Result X Failed

Fail Oil leaking continuously from engine posing a serious risk to road safety BETWEEN ENGINE AND GEAR BOX IN EXCESS OF PERMITTED LIMITS (8.4.1 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #13 2021-10-22 13:05

MOT test number 349226344902

Result ✓ Passed

Advice Front Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))

Advice Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Track rod end ball joint has slight play both side inner (2.1.3 (b) (i))

MOT #12 2020-11-05 12:46

MOT test number 470695976612

Result
✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11 2019-11-07 13:10

MOT test number 658194795503

Result
✓ Passed

CarCheck.co.uk page 4/13



MOT #10 2018-10-27 11:23 MOT test number 585757837632

MOT #9 2017-06-26 13:03

MOT test number 923466196749

Result ✓ Passed

MOT #8 2016-06-17 12:02

MOT test number 997159537003

Result \(\sqrt{Passed} \)

MOT #7 2015-06-26 15:01

MOT test number 577837975185

Result \rightarrow Passed

Notice Both rear tyres have cracks on outer sidewalls

MOT #6 2014-06-26 16:13

MOT test number 286697174154

Result
✓ Passed

Notice Unable to see rear brake pads

Notice Both rear tyres have surface cracks

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #5 2013-06-25 12:16

MOT test number 519276173148

Result

Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



MOT #2

GLO7NBJ report date: 2024-03-29

2011-06-14 15:45

MOT #4		2012-06-29 11:19
MOT test number		516191882153
Result		✓ Passed
MOT #3		2012-06-29 11:19
MOT test number		217521482136
Result		x Failed
Pass with rectification	Offside Front Headlamp aim too low (1.8)	

MOT test number	379155561167
Result	✓ Passed
MOT #1	2010-06-15 12:26
MOT test number	982156260151
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	4 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	

THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	UK ZIS
Plate since	
Current registration	OK OK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-06-22
Last registration	2023-12-05
Complete history	See info



Registration #1	2007-06-22	19 mi
Registration #2	2010-06-15	13.867 mi
Registration #3	2011-06-14	15.669 mi
Registration #4	2012-06-29	19.578 mi
Registration #5	2013-06-25	26.161 mi
Registration #6	2014-06-26	32.710 mi
Registration #7	2015-06-26	37.372 mi
Registration #8	2016-06-17	41.540 mi
Registration #9	2017-06-26	43.174 mi
Registration #10		71.777 es
Registration #11		11.177 mi
Registration #12		
		0.00
Registration #13		11.777 es
Registration #13 Registration #14		11.77 m
		11.777 es 11.777 es 11.777 es
Registration #14		11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
50567	
S0569	

Safety ratings

NCAP rating	未 未未未未
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1475 mm
Length	4045 mm
Wheel base	2500 mm
Kerb weight	1268 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

Engine number

G4EE7672847