





General information

Make	NISSAN
Model	NOTE ACENTA DIG-T XTRONIC
Colour	White
Year of manufacture	2015
Top speed	115 mph
0 - 60 mph	12.7 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	115 BHP
Max. torque	165 Nm at 2.000 rpm
Engine capacity	1.198 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С









Internet history

Entry 1	
Date	2021-02-03
Pictures	10
Listing price	View report









source: autoonline.co.uk



MOT history

MOT expiry date	2024-07-14
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	12
Total items failed	2

MOT #8		2023-06-28 11:13
MOT test	number	991750089840
Result		🗸 Passed
Next expi	ry date	2024-07-14
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2022-06-16 07:36
MOT test number	354853922465
Result	✓ Passed
Advice Nearside Suspension component ball joint has slight play (5.3.4 (a) (i))	

MOT #6	2021-07-15 10:44
MOT test number	853115850842
Result	✓ Passed

MOT #5	2021-03-19 16:33
MOT test number	523772906740
Result	✓ Passed
Advice Offside Front Lower Suspension arm pin or bush worn but no front bush (5.3.4 (a) (i))	ot resulting in excessive movement



GK15VKN
report date: 2024-03-29

MOT #4	2020-04-09 13:25
MOT test number	429169050598
Result	✓ Passed
Advice Nearside Front Brake pad(s) wearing thin brake pads getting low (1 Advice Handbrake travel slightly long Minor Nearside Front Windscreen wiper blade defective wiper blade split or	
screen (3.4 (b) (i))	
MOT #3	2019-05-04 08:18
MOT test number	121686110848
Result	✓ Passed

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect shock absorber very slightly leaking (5.3.2 (b))

Advice Brake disc worn, pitted or scored, but not seriously weakened both front brake discs lipped (1.1.14 (a) (ii))

Advice Handbrake travel slightly long

MOT #2	2018-03-27 09:33
MOT test number	473391255562
Result	✓ Passed

MOT #1	2018-03-19 11:21
MOT test number	883089074403
Result	🗙 Failed
Fail Brake performance not tested Not tested due to windscreen condition (3.7.A.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Front Windscreen has damage to an area in excess of a 10mm circle within zone 'A	۹' (8.3.1a)
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	



GK15VKN report date: 2024-03-29

Tax & MOT check

Tax due: 1 July 2024	✓ Taxed	Expires: 14 July 2024	✓ МОТ
Tax status			Valid until 1 July
Days left			64
MOT expiry date			14 July 2024
Full MOT history			See MOT history
Tax calculation			

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-04-24
Last registration	2023-06-28
Complete history	See info



Registration #1	2015-04-24	22 mi
Registration #2	2018-03-19	14.418 mi
Registration #3	2018-03-27	14.510 mi
Registration #4	2019-05-04	18.214 mi
Registration #5	2020-04-09	20.720 mi
Registration #6		11.777 esi
Registration #7		
Registration #7		11.777 mi
Registration #8		11.117 es
		11,117 46 11,117 46 11,117 46

More info >





Car features

S0225	Air conditioning
\$0295	
\$0482	
S0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	84%
Children	81%
Pedestrian	75%
Safety systems	68%
Overall rating	78%
Video	see crash video



Dimensions & weight	
Width	1768 mm
Height	1520 mm
Length	4385 mm
Wheel base	2700 mm
Kerb weight	1329 kg
Max. allowed weight	1750 kg
Additional information	
Fuel tank capacity	46
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	112791A