





report date: 2024-03-29

## General information

Make	VOLKSWAGEN
Model	CC TDI BLUEMOTION TECHNOLOGY DSG
Colour	Grey
Year of manufacture	2014
Top speed	132 mph
0 - 100 km/h	9.8 seconds
0 - 60 mph	9.8 seconds
Gearbox	6 speed Semi Auto

## Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	60.1 mpg
Consumption combined	53.3 mpg
CO2 emission	131 g/km
CO2 label	Е



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history

## Entry 1

Date 2021-08-07

Pictures 31

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

# MOT history

MOT expiry date	2024-07-26
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	10
Total items failed	4

MOT #9		2023-07-27 14:39
MOT test	number	475026091189
Result		✓ Passed
Next expi	ry date	2024-07-26
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excess	ssive movement (5.3.4
Advice	Offside Rear Suspension arm corroded but not seriously weakened (5.3.3	(b) (i))
Advice	Nearside Rear Suspension arm corroded but not seriously weakened (5.3.	3 (b) (i))

MOT #	8	2023-07-26 15:34
MOT te	est number	471579777077
Result		🗙 Failed
Fail	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Fail	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))	
Fail	Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of	dirt (5.3.4 (b) (ii))
<b>Advi</b> (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive m	ovement (5.3.4

MOT #7	2022-07-27 16:43
MOT test number	105762028180
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #6 2021-05-12 13:46

**MOT test number** 160509629974

**Result** ✓ Passed

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

MOT #5 2021-05-11 16:24

**MOT test number** 922550932973

**Result** X Failed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

**MOT #4** 2020-05-12 11:40

**MOT test number** 397775070487

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #3 2019-05-10 11:15

**MOT test number** 496107283123

**Result** ✓ Passed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #2** 2018-05-21 13:51

**MOT test number** 335429626899

Result 

Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

**MOT #1** 2017-09-28 08:52

**MOT test number** 838991693961

**Result** ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

## Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	26 July 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



#### Extra VOLKSWAGEN salvage check



**Category** 

**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dov here.	
**********	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK SIX
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-09-25
Last registration	2023-07-27
Complete history	See info



Registration #1	2014-09-25	15 mi
Registration #2	2017-09-28	26.328 mi
Registration #3	2018-05-21	29.850 mi
Registration #4	2019-05-10	37.746 mi
Registration #5	2020-05-12	45.637 mi
Registration #6	2021-05-11	51.323 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		19.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



## Dimensions & weight

Width	2090 mm
Height	1421 mm
Length	4902 mm
Wheel base	2710 mm
Kerb weight	1564 kg
Max. allowed weight	2070 kg

## Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
CarChack co.uk	nago 12/12

CarCheck.co.uk page 12/12

Number of axles	2
Engine number	CFFBK81075