





report date: 2024-03-29

General information

Make	MINI
Model	MINI (R60) COOPER D
Colour	Blue
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-08

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2025-04-16
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	15
Total items failed	0

MOT #13	2024-04-05 11:22
MOT test number	861328276063
Result	✓ Passed
Next expiry date	2025-04-16

MOT #12	2023-04-17 08:54
MOT test number	275616496721
Result	√ Passed

MOT #11		2023-04-04 07:51
MOT test	number	694077612675
Result		X Failed
MAJOR	Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))	
Advice	All tyres perished	

MOT #10		2022-03-17 15:41
MOT test	number	964782236184
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/12



MOT #9

OV600AM

report date: 2024-03-29

2021-04-07 13:25

MOT test number 673799807309

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8 2020-03-23 16:45

MOT test number 808698332353

Result \(\sqrt{Passed} \)

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7 2020-03-23 12:34

MOT test number 150666894423

Result X Failed

MAJOR Offside Rear Stop lamp(s) showing white light to the rear (4.3.3 (a) (ii))

MAJOR Offside Rear Position lamp showing white light to the rear (4.2.3 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6 2019-04-15 10:42

MOT test number 552158447618

Result \(\sqrt{Passed} \)

MOT #5 2018-04-03 13:00

MOT test number 860769985226

Result ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4		2017-04-05 10:28
MOT test	number	342851716258
Result		✓ Passed
Advice	Under tray covers fitted obscuring some underside components	
Advice	Offside Front Tyre worn close to the legal limit on 3mm (4.1.E.1)	
Advice	Top engine covers fitted obscuring some engine bay components	
Advice	Nearside Front Tyre worn close to the legal limit on 3mm (4.1.E.1)	

MOT #3	2016-04-04 14:58
MOT test number	651287250857
Result	✓ Passed
MOT #2	2015-02-03 09:09
MOT test number	435414635045
Result	✓ Passed
MOT #1	2014-01-07 09:24
MOT test number	919147304006
Result	✓ Passed
Notice Under-trays fitted obscuring some underside components	
Notice Vehicle's internal headlight adjuster altered to recheck lights	

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	16 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	NE NE
Plate since	
Current registration	NE NE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-11-03
Last registration	2024-04-05
Complete history	See info



Registration #1	2010-11-03	19 mi
Registration #2	2014-01-07	44.475 mi
Registration #3	2015-02-03	61.584 mi
Registration #4	2016-04-04	75.208 mi
Registration #5	2017-04-05	85.854 mi
Registration #6	2018-04-03	93.835 mi
Registration #7	2019-04-15	101.252 mi
Registration #8	2020-03-23	111.346 mi
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es
Registration #15		11.177 ms

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1577 mm
Length	4097 mm
Max. allowed weight	1820 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	72617589

CarCheck.co.uk page 12/12