



report date: 2024-03-29

General information

Make	AUDI
Model	A7 SPORTBACK TDI QUATTRO S LINE
Colour	Grey
Year of manufacture	2016
Top speed	155 mph
0 - 100 km/h	5.7 seconds
0 - 60 mph	5.7 seconds
Gearbox	7 speed Semi-Automatic

Engine & fuel consumption

Power	200 kW / 272 HP / 268 BHP
Max. torque	580 Nm at 1.250 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	56.5 mpg
Consumption combined	52.3 mpg
CO2 emission	142 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-12-19
Pictures	33
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-24
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	7
Total items failed	5

MOT #7	2024-03-25 14:32
MOT test number	278557942810
Result	✓ Passed
Next expiry date	2025-03-24

MOT #6	2023-01-31 11:16
MOT test number	944285522915
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Tyre slightly damaged (5.2.3 (d) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5	2021-12-01 15:56
MOT test number	301992659444
Result	✓ Passed

MOT #4	2021-01-22 12:33
MOT test number	533342228198
Result	✓ Passed
Advice	Nearside Rear Inner Brake pad(s) wearing thin close to wear indicator (1.1.13 (a) (ii))

**MOT #3**

2021-01-21 08:18

MOT test number

953891382035

Result**✗ Failed****Fail**

Offside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))

Fail

Nearside Front Tyre has a tear, caused by separation or partial failure of its structure inner sidewall (5.2.3 (d) (ii))

Fail

Nearside Front Outer Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

Advice

Nearside Rear Inner Brake pad(s) wearing thin close to wear indicator (1.1.13 (a) (ii))

Fail

Offside Front Tyre has a tear, caused by separation or partial failure of its structure inner and outer sidewalls - inner much worse (5.2.3 (d) (ii))

Fail

Nearside Front Inner Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

Advice

Nearside Front Outer Tyre slightly damaged slight damage no structure exposed (5.2.3 (d) (ii))

MOT #2

2020-03-23 13:49

MOT test number

682978169671

Result**✓ Passed****MOT #1**

2019-03-15 15:19

MOT test number

751979240710

Result**✓ Passed**



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
24 March 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	24 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-08-05
Last registration	2024-03-25
Complete history	See info



Registration #1	2016-08-05	14 mi
Registration #2	2019-03-15	16.052 mi
Registration #3	2020-03-23	22.382 mi
Registration #4	2021-01-21	24.633 mi
Registration #5	2021-01-22	24.635 mi
Registration #6	2022-03-20	25.277 mi
Registration #7	2022-03-20	25.277 mi
Registration #8	2022-03-20	25.277 mi
Registration #9	2022-03-20	25.277 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1911 mm
Height	1420 mm
Length	4974 mm
Wheel base	2914 mm
Kerb weight	1830 kg
Max. allowed weight	2440 kg

Additional information

Fuel tank capacity	73 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	CRTD081222