





report date: 2024-03-29

#### General information

Make	PEUGEOT
Model	5008 HDI SPORT
Colour	Blue
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

#### Engine & fuel consumption

Power	150 BHP
Max. torque 340 Nm at 2.000 rpm	
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/14



report date: 2024-03-29

#### Internet history

#### Entry 1

Date 2021-08-13

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

## MOT history

MOT expiry date	2024-08-23
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	40
Total items failed	8

MOT #16	2023-08-24 16:07
MOT test number	232482452448
Result	✓ Passed
Next expiry date	2024-08-23
Minor Central Stop lamp(s) light intensity obviously reduced (4.3.3 (a) (i))	
Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))	
Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))	
Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #15	2023-08-24 10:49
MOT test number	470457979527
Result	<b>×</b> Failed
Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))	
Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))	
Minor Central Stop lamp(s) light intensity obviously reduced (4.3.3 (a) (i))	
Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))	
Fail Windscreen washer not working (3.5 (a))	

CarCheck.co.uk page 3/14



Fail

**DK60WNO** 

report date: 2024-03-29

MOT #14	2022-07-23 11:57
MOT test number	765491575948
Result	✓ Passed
MOT #13	2021-08-19 10:39
MOT test number	613420961875
Result	✓ Passed
MOT #12	2021-08-17 15:02
MOT test number	592253445814
Result	<b>×</b> Failed
Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Fail Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	

Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #11	2020-11-02 13:58
MOT test	number 487606611670
Result	✓ Passed
Advice (a) (i))	Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Play in steering rack inner joint(s)
Advice	Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/14



report date: 2024-03-29

**MOT #10** 2020-11-02 13:58 **MOT** test number 822694556340 Result **X** Failed **Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Pass with rectification Nearside Headlamp aim too high (4.1.2 (a)) Advice Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Offside Front Play in steering rack inner joint(s) Advice Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #9** 2019-11-21 10:58 **MOT** test number 208947346971 Result ✓ Passed **Advice** Play in steering rack inner joint(s) slight play in steering rack inner joints Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** 

MOT #8	2018-11-05 09:52
MOT test number	809374671889
Result	<b>✓</b> Passed
Advice Front Play in steering rack inner joint(s)	

CarCheck.co.uk page 5/14



report date: 2024-03-29

Passed

MOT #7 2017-11-02 09:19

**MOT test number** 485297776267

MOT #6 2016-11-24 10:46

**MOT test number** 535923310902

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2015-11-18 08:41

**MOT test number** 775435701962

**Result** 
✓ Passed

Advice Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

MOT #4 2015-11-17 14:54

**MOT test number** 514271257655

**Result** X Failed

**Advice** N/s/f tyre bald inner edge

Result

Advice Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #3 2014-11-01 10:13

MOT test number 858765004306

----


Advice Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

CarCheck.co.uk page 6/14



report date: 2024-03-29



MOT #1		2013-11-23 10:18
MOT test	number	875097023393
Result		✓ Passed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)	
Notice	Has a cut in sidewall not in excess of the requirements deep enough to reach the ply or cords.	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

CarCheck.co.uk page 7/14



DK60WNO report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	23 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

$\sim$				
-( )v	vner	hi	ะะก	ı۲
$\sim$ v	V I C I		,,,,	

		_
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		
THE STATE OF THE S		
***************************************		
***************************************		
********		
***************************************		
	More info >	
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		9
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 11/14



report date: 2024-03-29

#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

**Contact info** 

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-11-30
Last registration	2023-08-24
Complete history	See info



Registration #1	2010-11-30	8 mi
Registration #2	2013-11-23	36.488 mi
Registration #3	2014-10-31	46.799 mi
Registration #4	2014-11-01	46.799 mi
Registration #5	2015-11-17	58.583 mi
Registration #6	2015-11-18	58.609 mi
Registration #7	2016-11-24	70.927 mi
Registration #8	2017-11-02	80.919 mi
Registration #9	2018-11-05	89.963 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		111,7177 mg

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

## Car features

S0225	Air conditionin
S0295	
50482	
50501	
60566	
60567	
50569	

## Safety ratings

NCAP rating	****
Adult	89%
Children	79%
Pedestrian	37%
Safety systems	97%
Overall rating	77%
Video	see crash video



## Dimensions & weight

Width	2118 mm
Height	1638 mm
Length	4530 mm
Wheel base	2727 mm
Kerb weight	1668 kg
Max. allowed weight	2310 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 14/14

Number of axles 2

**Engine number** DYWS4014993