



**WR08ZZN**


report date: 2024-03-28

General information

Make	CITROEN
Model	BERLINGO HDI VTR PLUS EGS GRAND PICASSO
Colour	Silver
Year of manufacture	2008
Top speed	112 mph
0 - 60 mph	13.4 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	49.6 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-11
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-06-27
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	12
Total items failed	7

MOT #15	2023-06-28 12:40
MOT test number	860354799977
Result	✓ Passed
Next expiry date	2024-06-27

MOT #14	2023-06-13 07:46
MOT test number	969843382358

Result	✗ Failed
--------	----------

- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Fail** Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Minor** Nearside Front Electrical wiring inadequately secured abs fouling wheel (4.11 (a) (i))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #13	2022-05-30 12:12
MOT test number	322231518427

Result	✓ Passed
--------	----------

**MOT #12** 2022-05-26 10:32**MOT test number** 560140630780**Result** ✗ Failed**Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #11** 2021-06-09 11:29**MOT test number** 355153548908**Result** ✓ Passed**MOT #10** 2020-05-11 12:25**MOT test number** 769455195557**Result** ✓ Passed**Advice** Rear tyres slightly perished**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #9** 2019-05-07 11:16**MOT test number** 935547808915**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #8** 2018-05-09 09:29**MOT test number** 291568282599**Result** ✓ Passed



<b>MOT #7</b>	2017-05-11 10:30
<b>MOT test number</b>	430138964039
<b>Result</b>	✓ Passed
<b>MOT #6</b>	2016-05-10 12:50
<b>MOT test number</b>	968989783416
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Front Brake pad(s) wearing thin (3.5.1g)
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
<b>MOT #5</b>	2015-05-14 09:19
<b>MOT test number</b>	239094635494
<b>Result</b>	✓ Passed
<b>MOT #4</b>	2014-05-16 11:19
<b>MOT test number</b>	575426734126
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2013-05-10 12:21
<b>MOT test number</b>	539200333194
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2012-05-14 11:05
<b>MOT test number</b>	477935232176
<b>Result</b>	✓ Passed
<b>MOT #1</b>	2011-05-17 10:58
<b>MOT test number</b>	267517331458
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
27 June 2024

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	27 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>WR08ZZN</b>
Plate since	2019-09-28
Current registration	<b>WR08ZZN</b>
Plate since	2019-09-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-06-05
Last registration	2023-06-28
Complete history	<a href="#">See info</a>



Registration #1	2008-06-05	12 mi
Registration #2	2011-05-17	13.167 mi
Registration #3	2012-05-14	18.561 mi
Registration #4	2013-05-10	24.406 mi
Registration #5	2014-05-16	30.820 mi
Registration #6	2015-05-14	35.511 mi
Registration #7	2016-05-10	39.042 mi
Registration #8	2017-05-11	42.271 mi
Registration #9	2018-05-09	45.148 mi
Registration #10	2019-05-09	48.025 mi
Registration #11	2020-05-09	50.902 mi
Registration #12	2021-05-09	53.779 mi
Registration #13	2022-05-09	56.656 mi
Registration #14	2023-05-09	59.533 mi
Registration #15	2024-05-09	62.410 mi
Registration #16	2025-05-09	65.287 mi
Registration #17	2026-05-09	68.164 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1829 mm
Height	1700 mm
Length	4585 mm
Wheel base	2728 mm
Kerb weight	1539 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBBN0005798