





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	ARTEON ELEGANCE TDI DSG
Colour	Silver
Year of manufacture	2018
Top speed	136 mph
0 - 100 km/h	9.1 seconds
0 - 60 mph	8.8 seconds
Gearbox	7 speed Semi Auto

Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	116 g/km
CO2 label	С



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2022-03-24

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-06-06
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	10
Total items failed	3

MOT #4	2023-06-02 15:09
MOT test number	292601487740
Result	✓ Passed
Next expiry date	2024-06-06

MOT #3	2022-05-21 09:31
MOT test number	886478864157
Result	✓ Passed

MOT #2		2021-05-20 09:03
MOT test	number	331545586743
Result		✓ Passed
Advice	Offside Front Brake disc worn, but not excessively Disc lipped. (1.1.14 (a) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Worn on Inner edge. (5.2.3 (e))
Advice	Nearside Front Brake disc worn, but not excessively Disc lipped. (1.1.14 (a) (i))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge Worn on Inner edge.	(5.2.3 (e))

CarCheck.co.uk page 3/11



MOT #1 2021-05-14 15:42

MOT test number 335653474358

Result × Failed **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn on Inner edge. (5.2.3 (e)) **Advice** Nearside Front Brake disc worn, but not excessively Disc lipped. (1.1.14 (a) (i)) Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Advice Offside Rear Tyre worn close to legal limit/worn on edge Worn on Inner edge. (5.2.3 (e)) Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm. (5.2.3 (e)) Offside Front Brake disc worn, but not excessively Disc lipped. (1.1.14 (a) (i)) Advice **Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn on Inner edge. (5.2.3 (e)) Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	6 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e union matery	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK.
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-06-07
Last registration	2023-06-02
Complete history	See info



Registration #1	2018-06-07	29 mi
Registration #2	2021-05-14	77.971 mi
Registration #3	2021-05-20	77.971 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		0.777-46

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	96%
Children	85%
Pedestrian	85%
Safety systems	82%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1871 mm
Height	1450 mm
Length	4862 mm
Wheel base	2837 mm
Kerb weight	1643 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	66 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	nago 11/11

CarCheck.co.uk page 11/11

Number of seats	5
Number of axles	2
Engine number	DFGA484312