



report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D3 SE LUX
Colour	Grey
Year of manufacture	2013
Top speed	127 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	350 Nm at 2.250 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-07-01
Pictures	9
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-31
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	23
Total items failed	10

MOT #13	2023-08-31 13:29
MOT test number	362616959359
Result	✓ Passed
Next expiry date	2024-08-31

MOT #12	2023-08-31 09:15
MOT test number	112608571236
Result	✗ Failed
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Nearside Front Tyre has ply or cords exposed 235/40/18 (5.2.3 (d) (ii))

MOT #11	2022-08-09 13:31
MOT test number	287160991225
Result	✓ Passed

**MOT #10** 2022-08-09 09:21**MOT test number** 892085191993**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed inner edge worn down to cords (5.2.3 (d) (ii))**Fail** Nearside Rear Tyre has ply or cords exposed outer sidewall (5.2.3 (d) (ii))**Fail** Offside Front Tyre has ply or cords exposed inner edge worn down to cords (5.2.3 (d) (ii))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #9** 2021-08-19 09:41**MOT test number** 507472555882**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Engine covers and undertrays fitted**MOT #8** 2021-08-19 09:41**MOT test number** 673817436326**Result** ✗ Failed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Engine covers and undertrays fitted**MOT #7** 2020-09-01 14:27**MOT test number** 910965253901**Result** ✓ Passed**Advice** Power steering close to minimum mark (2.1.5 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Nail in tyre

**MOT #6**

2020-09-01 14:27

**MOT test number**

399299494178

**Result****✗ Failed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Nail in tyre**Pass with rectification** Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))**Advice** Power steering close to minimum mark (2.1.5 (b) (i))**MOT #5**

2019-08-17 11:29

**MOT test number**

993808800780

**Result****✓ Passed****MOT #4**

2019-08-17 10:02

**MOT test number**

178374004424

**Result****✗ Failed****Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #3**

2018-08-20 14:58

**MOT test number**

478051222203

**Result****✓ Passed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Engine cover and Under-Tray cover fitted**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #2	2017-09-06 10:41
MOT test number	307150234632
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit edge worn (4.1.E.1)
Advice	Rear Wrong Brake pads fitted
Advice	Child Seat fitted not allowing full inspection of adult belt
Advice	Unusual noise coming from axillary belt area
Advice	Front brake disc worn, pitted or scored, but not seriously weakened lipped (3.5.1i)

MOT #1	2016-09-23 15:53
MOT test number	732096776799
Result	✓ Passed
Advice	Offside Rear tyre wearing low on inside edge
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside front brake fluctuating, but not excessively (3.7.B.3)



Tax & MOT check

X

Untaxed

Tax expired:  
22 April 2024

✓

MOT

Expires:  
31 August 2024

Tax status	Expired at 22 April 2024
Days left	7 days too late
MOT expiry date	31 August 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-10-04
Last registration	2023-08-31
Complete history	<a href="#">See info</a>



Registration #1	2013-10-04	22 mi
Registration #2	2016-09-23	52.514 mi
Registration #3	2017-09-06	59.081 mi
Registration #4	2018-08-20	62.472 mi
Registration #5	2019-08-17	68.604 mi
Registration #6	2019-08-17	68.604 mi
Registration #7	2020-09-01	71.086 mi
Registration #8	2020-09-01	71.086 mi
Registration #9	2020-09-01	71.086 mi
Registration #10	2020-09-01	71.086 mi
Registration #11	2020-09-01	71.086 mi
Registration #12	2020-09-01	71.086 mi
Registration #13	2020-09-01	71.086 mi
Registration #14	2020-09-01	71.086 mi
Registration #15	2020-09-01	71.086 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1605 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	1259958
---------------	---------