



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D S
Colour	Black
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





MOT history

MOT expiry date	2021-03-13
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	14
Total items failed	7

MOT #14	2020-03-12 12:00
MOT test number	473299125295
Result	✓ Passed
Next expiry date	2021-03-13
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2020-03-11 10:58
MOT test number	224601611418
Result	✗ Failed
MAJOR	Nearside Headlamp aim too low (4.1.2 (a))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Exhaust has a major leak of exhaust gases (6.1.2 (a))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2019-03-12 16:33
MOT test number	719371465656
Result	✓ Passed

**MOT #11** 2019-03-12 11:15**MOT test number** 325437618760**Result** ✗ Failed**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**DANGEROUS** Nearside Rear Brake lining(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #10** 2018-03-13 10:00**MOT test number** 323125279297**Result** ✓ Passed**MOT #9** 2017-03-13 10:04**MOT test number** 835714534312**Result** ✓ Passed**MOT #8** 2016-03-14 14:28**MOT test number** 364452963873**Result** ✓ Passed**Advice** Nsr tyre spliting**MOT #7** 2016-03-07 14:25**MOT test number** 541382538182**Result** ✗ Failed**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nsr tyre spliting**MOT #6** 2015-02-07 09:17**MOT test number** 669408535033**Result** ✓ Passed

**MOT #5** 2015-02-06 11:07**MOT test number** 599477435067**Result** ✗ Failed**Fail** Nearside front brake excessively fluctuating (3.7.B.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside front brake excessively fluctuating (3.7.B.3)**MOT #4** 2014-04-03 11:26**MOT test number** 629753894072**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-04-16 12:01**MOT test number** 218236403186**Result** ✓ Passed**MOT #2** 2012-08-02 12:44**MOT test number** 177945712287**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside front brake juddering slightly (3.7.A.2b)**MOT #1** 2012-08-02 12:44**MOT test number** 448955312214**Result** ✓ Passed**Advice** Nearside front brake juddering slightly (3.7.A.2b)



Tax & MOT check

✕
Untaxed

Tax expired:
31 December 2020

✕
MOT

Expired:
13 March 2021

Tax status	Expired at 31 December 2020
Days left	1216 days too late
MOT expiry date	13 March 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	DA09YRG
Plate since	2024-03-29
Current registration	DA09YRG
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-07-31
Last registration	2020-03-12
Complete history	See info



Registration #1	2009-07-31	12 mi
Registration #2	2012-08-02	76.255 mi
Registration #3	2013-04-16	82.204 mi
Registration #4	2014-04-03	90.015 mi
Registration #5	2015-02-06	95.104 mi
Registration #6	2015-02-07	95.105 mi
Registration #7	2016-03-07	101.874 mi
Registration #8	2016-03-07	101.874 mi
Registration #9	2016-03-07	101.874 mi
Registration #10	2016-03-07	101.874 mi
Registration #11	2016-03-07	101.874 mi
Registration #12	2016-03-07	101.874 mi
Registration #13	2016-03-07	101.874 mi
Registration #14	2016-03-07	101.874 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1446 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	591583
---------------	--------