



MLI4WUM


report date: 2024-03-28

General information

Make	FORD
Model	MONDEO ZETEC BUSINESS EDITION TDCI
Colour	Blue
Year of manufacture	2014
Top speed	118 mph
0 - 100 km/h	11.2 seconds
0 - 60 mph	11.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	85 kW / 116 HP / 113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	109 g/km
CO2 label	B





MOT history

MOT expiry date	2021-09-02
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	30
Total items failed	0

MOT #9	2020-09-03 08:51
MOT test number	257384943447
Result	✓ Passed
Next expiry date	2021-09-02
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #8	2020-02-14 15:44
MOT test number	396664873772
Result	✓ Passed



MOT #72019-08-23 16:12

MOT test number884579426595

Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge AND UNEVENLY WORN (5.2.3 (e))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge AND DETERIATED (5.2.3 (e))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Play in steering rack inner joint(s)	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

**MOT #6**

2019-08-23 14:21

**MOT test number**

998667602935

**Result****✗ Failed**

**MAJOR** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge AND UNEVENLY WORN (5.2.3 (e))

**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Play in steering rack inner joint(s)

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MAJOR** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge AND DETERIATED (5.2.3 (e))

**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #5**

2019-02-15 16:14

**MOT test number**

279344236596

**Result****✓ Passed**

**MOT #4** 2019-02-15 13:33**MOT test number** 671935879535**Result** ✗ Failed**DANGEROUS** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Offside Front Position lamp not working (4.2.1 (a))**MAJOR** Offside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a))**MAJOR** Nearside Front Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))**MOT #3** 2018-08-22 14:13**MOT test number** 869526514174**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #2** 2017-08-25 09:00**MOT test number** 113089851332**Result** ✓ Passed**MOT #1** 2017-05-15 14:20**MOT test number** 266269247763**Result** ✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
14 January 2021

✕  
MOT

Expired:  
2 September 2021

Tax status	Expired at 14 January 2021
Days left	1201 days too late
MOT expiry date	2 September 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>ML14WUM</b>
Plate since	2019-03-28
Current registration	<b>ML14WUM</b>
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-06-02
Last registration	2020-09-03
Complete history	<a href="#">See info</a>



Registration #1	2014-06-02	26 mi
Registration #2	2017-05-15	87.958 mi
Registration #3	2017-08-25	89.844 mi
Registration #4	2018-08-22	121.040 mi
Registration #5	2019-02-15	135.790 mi
Registration #6	2019-05-20	151.277 mi
Registration #7	2019-08-20	161.277 mi
Registration #8	2019-11-20	171.277 mi
Registration #9	2020-02-20	181.277 mi
Registration #10	2020-05-20	191.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2092 mm
Height	1500 mm
Length	4784 mm
Wheel base	2850 mm
Kerb weight	1396 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	EJ26323