





report date: 2024-03-29

### General information

Make	LEXUS
Model	NX 300H PREMIER
Colour	Blue
Year of manufacture	2015
Top speed	112 mph
0 - 60 mph	9.3 seconds
Gearbox	1 speed CVT

### Engine & fuel consumption

Power	194 BHP
Max. torque	480 Nm at 4.200 rpm
Engine capacity	2.494 сс
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	53.3 mpg
Consumption extra urban	55.4 mpg
Consumption combined	54.3 mpg
CO2 emission	121 g/km
CO2 label	D



CarCheck.co.uk page 1/11



## Internet history

_	_	_		_	-
드	n	C	ľν	7	1

Lifety 1	
Date	2021-06-22
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-10-03
MOT pass rate	100 %
MOT passed	6
Failed MOT tests	0
Total advice items	1
Total items failed	0

MOT #6	2023-09-06 09:58
MOT test number	365029153558
Result	<b>✓</b> Passed
Next expiry date	2024-10-03

MOT #5	2022-09-05 10:35
MOT test number	291819579135
Result	✓ Passed

MOT #4	2021-10-04 09:03
MOT test number	352128458017
Result	✓ Passed

MOT #3	2020-08-28 13:35
MOT test number	240533004771

Result ✓ Passed

**Advice** Under-trays fitted obscuring some underside components, engine covers fitted obscuring some components in the engine bay

MOT #2	2019-09-04 09:50
MOT test number	537823278841
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #1 2018-11-29 17:02

**MOT test number** 782980064448

CarCheck.co.uk page 4/11



### Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	3 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	59
Band	D
Single payment (12 months)	£ 140,00,-
Single six month payment	£ 77,00,-
Total payable by 12 monthly instalments	£ 147,00,-

CarCheck.co.uk page 5/11



LL650EA

report date: 2024-03-29

#### Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra LEXUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this LEXUS? How many owners did this L have? Check it in the premium report and see all owner registrations. Download the full report here.  More Plate changes  See in this check if this LEXUS had different number plates.	<u>e</u> .
Plate changes	
Plate changes	inte
Plate changes	inte
Plate changes	into
Plate changes	infa
Plate changes	infa
Plate changes	info
	11110
See in this check if this LEXUS had different number plates.	
Number of plates	
	,
UK UK	EFFEE
Plate since	
NEW TOTAL CONTROL OF THE PROPERTY OF THE PROPE	TTTTTT
Plate since	
More	
	info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LEXUS is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte at Info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2015-11-13
Last registration	2023-09-06
Complete history	See info



Registration #1	2015-11-13	23 mi
Registration #2	2018-11-29	14.197 mi
Registration #3	2019-09-04	24.385 mi
Registration #4	2020-08-28	35.814 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

7070.75.25

Registration #8

More info >

77,777 86

CarCheck.co.uk page 10/11



## Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
60569	

# Safety ratings

NCAP rating	****
Adult	82%
Children	82%
Pedestrian	69%
Safety systems	71%
Overall rating	77%
Video	see crash video



## Dimensions & weight

Width	1845 mm
Height	1645 mm
Length	4630 mm
Wheel base	2660 mm
Kerb weight	1785 kg
Max. allowed weight	2395 kg

## Additional information

Fuel tank capacity	56 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

Engine number 2AR1131905