



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2300 L1H1 CDTI S/S ECOFLEX
Colour	Silver
Year of manufacture	2014
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	126 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-08-10
Pictures	11
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-04
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	18
Total items failed	19

MOT #13	2023-08-05 09:56
MOT test number	394683971246
Result	✓ Passed
Next expiry date	2024-08-04
Advice	Rear Exhaust mounting defective (6.1.2 (a))

MOT #12	2022-06-29 12:52
MOT test number	518005304479
Result	✓ Passed

MOT #11	2021-07-22 20:02
MOT test number	330338331919
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2021-07-22 20:02

**MOT test number**

428536858791

**Result**

✗ Failed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9**

2021-03-04 14:14

**MOT test number**

307829076903

**Result**

✓ Passed

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing outer sidewalls (5.2.3 (d) (ii))**MOT #8**

2021-03-02 12:52

**MOT test number**

914542971516

**Result**

✗ Failed

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Fail** Anti-roll bar linkage ball joint excessively worn both front (5.3.4 (a) (i))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing outer sidewalls (5.2.3 (d) (ii))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Horn not working (7.7 (a) (ii))

**MOT #7** 2020-02-27 11:21**MOT test number** 487365266461**Result** ✓ Passed

- Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Injector Blowing On Engine
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #6** 2020-02-27 11:21**MOT test number** 362800433441**Result** ✗ Failed

- Pass with rectification** Brake pedal anti-slip provision missing (1.1.2 (c))
- Advice** Injector Blowing On Engine
- Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Pass with rectification** Headlamp aim too high Both (4.1.2 (a))

**MOT #5** 2019-02-25 09:48**MOT test number** 717103857496**Result** ✓ Passed

- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Handbrake travel

**MOT #4** 2018-03-02 15:31**MOT test number** 431016123719**Result** ✓ Passed**MOT #3** 2018-02-21 15:32**MOT test number** 415090708211**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Fail** Brake pedal anti-slip provision missing (3.3.A.1b)**MOT #2** 2017-02-28 08:21**MOT test number** 129287346534**Result** ✓ Passed**MOT #1** 2017-02-27 09:50**MOT test number** 727140127018**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
4 August 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	4 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 DV63UZT
Plate since	2024-03-29
Current registration	 DV63UZT
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-02-27
Last registration	2023-08-05
Complete history	<a href="#">See info</a>



Registration #1	2014-02-27	19 mi
Registration #2	2017-02-27	62.576 mi
Registration #3	2017-02-28	62.576 mi
Registration #4	2018-02-21	87.674 mi
Registration #5	2018-03-02	87.674 mi
Registration #6	2019-02-25	98.429 mi
Registration #7	2020-02-27	104.868 mi
Registration #8	2020-02-27	104.868 mi
Registration #9	2020-03-27	105.377 mi
Registration #10	2020-03-27	105.377 mi
Registration #11	2020-03-27	105.377 mi
Registration #12	2020-03-27	105.377 mi
Registration #13	2020-03-27	105.377 mi
Registration #14	2020-03-27	105.377 mi
Registration #15	2020-03-27	105.377 mi

More info >



Dimensions & weight

Width	2119 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1290 kg
Max. allowed weight	2320 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A20005483853 LN9