



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	MR2 VVTi
Colour	Silver
Year of manufacture	2000
Top speed	127 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-04-03
Pictures	4
Listing price	View report




AA

This dealer has signed up to our **Dealer Promise.**

- Free history check
- 6 months (minimum) MOT
- Free 12 months Breakdown cover

aacars.com



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-08
MOT pass rate	86 %
MOT passed	19
Failed MOT tests	3
Total advice items	46
Total items failed	4

MOT #22	2024-03-26 11:41
MOT test number	566793104786
Result	✓ Passed
Next expiry date	2025-04-08
Advice	Sump pan corroded
Advice	Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened inner faces (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive around gearbox bell housing (8.4.1 (a) (i))
Advice	Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))

**MOT #21**

2024-03-26 11:41

MOT test number

358508969784

Result**✗ Failed****Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Advice** Oil leak, but not excessive around gearbox bell housing (8.4.1 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened inner faces (1.1.14 (a) (ii))**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**Pass with rectification** Offside Front Seat belt retracting mechanism defective (7.1.2 (e))**Advice** Sump pan corroded**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))**MOT #20**

2023-04-05 10:37

MOT test number

451035389190

Result**✓ Passed****Advice** O/s park brake efficiency down**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #19**

2023-04-05 08:53

MOT test number

264271234948

Result**✗ Failed**

- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** O/s park brake efficiency down
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

MOT #18

2022-04-09 09:56

MOT test number

806987513810

Result**✓ Passed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #17

2021-08-23 14:56

MOT test number

118055107491

Result**✓ Passed**

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #16** 2020-08-19 09:19**MOT test number** 747662094209**Result** ✓ Passed**MOT #15** 2019-08-02 15:28**MOT test number** 413451250412**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #14** 2018-08-08 14:22**MOT test number** 454379168047**Result** ✓ Passed**Advice** Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))**Advice** All tyres cracking**MOT #13** 2017-08-24 09:13**MOT test number** 240377787436**Result** ✓ Passed**Advice** Slight coolant leak from o/s front pipe**Advice** Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #12** 2017-08-24 09:13**MOT test number** 982719926151**Result** ✗ Failed**Advice** Slight coolant leak from o/s front pipe**Advice** Rear Brake pipe slightly corroded (3.6.B.2c)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #11** 2015-05-13 09:04**MOT test number** 769883435166**Result** ✓ Passed**Notice** Sight paint damage to front bumper on n/s**Notice** O/s rear shock absorber possibly slightly damp**MOT #10** 2014-05-31 08:30**MOT test number** 395951154189**Result** ✓ Passed**MOT #9** 2013-06-01 10:34**MOT test number** 259372653439**Result** ✓ Passed**Notice** O/s wiper blade torn**MOT #8** 2012-05-18 12:24**MOT test number** 199509132115**Result** ✓ Passed**MOT #7** 2011-06-01 15:27**MOT test number** 326102851143**Result** ✓ Passed

**MOT #6** 2009-11-21 10:47**MOT test number** 873735929331**Result** ✓ Passed**Advice** Offside Front brake disc slightly pitted (3.5.1h)**Notice** Front number plate starting to discolour**MOT #5** 2008-11-28 16:02**MOT test number** 170333338355**Result** ✓ Passed**Advice** Front brake disc slightly pitted (3.5.1h)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2007-11-28 10:48**MOT test number** 592042937308**Result** ✓ Passed**MOT #3** 2006-11-28 10:54**MOT test number** 162772236396**Result** ✓ Passed**MOT #2** 2005-11-23 11:30**MOT test number** 554757325353**Result** ✓ Passed**MOT #1** 2005-11-23 11:23**MOT test number** 892307125331**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
8 April 2025

Tax status		Valid until 1 April
Days left		337
MOT expiry date		8 April 2025
Full MOT history		See MOT history



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	X594GFP
Plate since	2019-03-28
Current registration	X594GFP
Plate since	2019-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2000-12-07
Last registration	2024-03-26
Complete history	See info



Registration #1	2000-12-07	23 mi
Registration #2	2005-11-23	41.518 mi
Registration #3	2005-11-23	41.518 mi
Registration #4	2006-11-28	45.731 mi
Registration #5	2007-11-28	49.769 mi
Registration #6	2008-11-28	53.932 mi
Registration #7	2009-11-21	57.947 mi
Registration #8	2011-06-01	64.665 mi
Registration #9	2012-05-18	72.425 mi
Registration #10	2013-06-01	78.291 mi
Registration #11	2014-05-31	82.967 mi
Registration #12	2015-05-13	87.353 mi
Registration #13	2016-05-13	91.739 mi
Registration #14	2017-05-13	96.125 mi
Registration #15	2018-05-13	100.511 mi
Registration #16	2019-05-13	104.897 mi
Registration #17	2020-05-13	109.283 mi
Registration #18	2021-05-13	113.669 mi
Registration #19	2022-05-13	118.055 mi
Registration #20	2023-05-13	122.441 mi
Registration #21	2024-03-26	126.827 mi
Registration #22		
Registration #23		
Registration #24		

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Max. allowed weight	1565 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	1ZZ0571529