



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Silver
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 1.900 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	176 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-05-24
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-01-31
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	32
Total items failed	19

MOT #13	2023-02-01 11:16
MOT test number	393826358515
Result	✓ Passed
Next expiry date	2024-01-31

MOT #12	2022-01-14 11:34
MOT test number	692223478953
Result	✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #11	2021-01-18 15:01
MOT test number	844170150705
Result	✓ Passed
Advice	Items removed from driver's view prior to test items on windscreen
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #10**

2021-01-14 12:21

MOT test number

924599229104

Result

✗ Failed

- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Lower Suspension arm ball joint likely to become detached split pin missing (5.3.4 (a) (ii))
- Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Items removed from driver's view prior to test items on windscreen
- Fail** Nearside Front Lower Suspension arm ball joint likely to become detached split pin missing (5.3.4 (a) (ii))
- Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))

MOT #9

2020-01-23 13:28

MOT test number

853912068727

Result

✓ Passed

- Advice** Brake pipe corroded, covered in grease or other material both front to rears (1.1.11 (c))

MOT #8

2020-01-21 11:49

MOT test number

325911142428

Result

✗ Failed

- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake pipe corroded, covered in grease or other material both front to rears (1.1.11 (c))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #7** 2019-01-24 13:28**MOT test number** 649793768823**Result** ✓ Passed

- Advice** Items removed from driver's view prior to test items on mirror and screen
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Central Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside rear seat belt webbing just starting to fray

MOT #6 2019-01-23 10:51**MOT test number** 982798098280**Result** ✗ Failed

- Advice** Nearside rear seat belt webbing just starting to fray
- Advice** Central Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Front Position lamp not working (4.2.1 (a))
- Advice** Items removed from driver's view prior to test items on mirror and screen
- Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #5 2018-01-26 12:58**MOT test number** 393356291957**Result** ✓ Passed

- Advice** Undertrays fitted

**MOT #4**

2017-01-26 09:48

MOT test number

901346316780

Result

✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #3**

2017-01-23 16:41

MOT test number

628072269033

Result

✗ Failed

Fail Offside Rear Wheel nut(s) missing (4.2.A.1e)**Fail** Offside Headlamp adversely affected by the operation of another lamp (1.7.5c)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Wheel nut(s) missing (4.2.A.1e)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Fail** Nearside Rear Wheel nut(s) missing (4.2.A.1e)**Fail** Parking brake: efficiency below requirements (3.7.C.1b)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Wheel bolt(s) missing (4.2.A.1e)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)



MOT #2	2016-02-11 09:18
MOT test number	122661448516
Result	✓ Passed

MOT #1	2015-02-04 10:42
MOT test number	598045235076
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
13 August 2023

✕
MOT

Expired:
31 January 2024

Tax status	Expired at 13 August 2023
Days left	260 days too late
MOT expiry date	31 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EY12ZVN
Plate since	2019-09-28
Current registration	EY12ZVN
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-03-01
Last registration	2023-02-01
Complete history	See info



Registration #1	2012-03-01	27 mi
Registration #2	2015-02-04	32.802 mi
Registration #3	2016-02-11	43.013 mi
Registration #4	2017-01-23	48.821 mi
Registration #5	2017-01-26	48.826 mi
Registration #6	2018-01-26	60.077 mi
Registration #7	2019-01-23	71.250 mi
Registration #8	2019-01-24	71.255 mi
Registration #9	2019-01-25	71.257 mi
Registration #10	2019-01-26	71.259 mi
Registration #11	2019-01-27	71.261 mi
Registration #12	2019-01-28	71.263 mi
Registration #13	2019-01-29	71.265 mi
Registration #14	2019-01-30	71.267 mi
Registration #15	2019-01-31	71.269 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1760 mm
Length	4660 mm
Wheel base	2700 mm
Kerb weight	1920 kg
Max. allowed weight	2570 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	D4HBBU548086
---------------	--------------