



WNI4VJZ

report date: 2024-03-28

General information

Make	FIAT
Model	500C S
Colour	Red
Year of manufacture	2014
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	58.9 mpg
CO2 emission	113 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-12-29
Pictures	11
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-28
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	24
Total items failed	5

MOT #102024-03-01 13:22

MOT test number542042223181

Result✓ Passed

Next expiry date2025-02-28

- Advice

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Front Macpherson strut pin or bush worn but not resulting in excessive movement Offside and Nearside top strut mounts (5.3.4 (a) (i))
- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #9** 2024-02-23 12:11**MOT test number** 471299516655**Result** ✗ Failed**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 195/45r16 (5.2.3 (d) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Macpherson strut pin or bush worn but not resulting in excessive movement Offside and Nearside top strut mounts (5.3.4 (a) (i))**Fail** Offside Driver's door cannot be opened from outside the vehicle (6.2.3 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Windscreen wiper does not clear the windscreen effectively Flat blades (3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #8** 2023-04-03 09:54**MOT test number** 424905455163**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Tyre slightly damaged/cracking or perishing both front (5.2.3 (d) (ii))

**MOT #7** 2022-02-08 15:31**MOT test number** 200558124171**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #6** 2021-01-29 08:31**MOT test number** 561123537571**Result** ✓ Passed**MOT #5** 2020-02-20 08:56**MOT test number** 315159055127**Result** ✓ Passed**MOT #4** 2019-02-18 09:53**MOT test number** 561189697318**Result** ✓ Passed**MOT #3** 2018-03-14 16:14**MOT test number** 563973139617**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2018-03-14 10:21**MOT test number** 337788504700**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner sidewall has cuts and cracks all along it showing cords when under load (4.1.D.1a)



MOT #1	2017-03-06 15:42
MOT test number	375129555189
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
28 February 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	28 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-04-01
Last registration	2024-03-01
Complete history	<a href="#">See info</a>



Registration #1	2014-04-01	21 mi
Registration #2	2017-03-06	23.549 mi
Registration #3	2018-03-14	35.362 mi
Registration #4	2018-03-14	35.362 mi
Registration #5	2019-02-18	44.347 mi
Registration #6	2020-02-20	45.446 mi
Registration #7	2020-03-20	55.277 mi
Registration #8	2020-03-20	55.277 mi
Registration #9	2020-03-20	55.277 mi
Registration #10	2020-03-20	55.277 mi
Registration #11	2020-03-20	55.277 mi
Registration #12	2020-03-20	55.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	0709926