



report date: 2024-03-29

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	White
Year of manufacture	2013
Top speed	117 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-07-21
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-19
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	2
Total items failed	15

MOT #12	2023-07-17 13:11
MOT test number	875118214199
Result	✓ Passed
Next expiry date	2024-07-19

MOT #11	2022-07-16 15:46
MOT test number	618396951518
Result	✓ Passed

**MOT #10**

2022-07-16 09:19

MOT test number

576188793499

Result**✗ Failed**

- Fail** Offside Rear Seat belt not functioning as intended (7.1.2 (c))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Reversing lamp inoperative (4.6.1 (a))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #9

2021-07-20 09:25

MOT test number

872092532901

Result**✓ Passed****MOT #8**

2021-07-19 14:01

MOT test number

790429900488

Result**✗ Failed**

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened pitted on inner surface (1.1.14 (a) (ii))
- Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Front Coil spring fractured or broken broken (5.3.1 (b) (i))
- Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))



MOT #7	2020-11-06 15:08
---------------	------------------

MOT test number	300520776086
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2019-04-27 08:52
---------------	------------------

MOT test number	859651386854
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2018-05-03 12:07
---------------	------------------

MOT test number	291726969007
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2017-03-16 13:31
---------------	------------------

MOT test number	387337706558
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2017-03-16 11:15
---------------	------------------

MOT test number	205413664519
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
-------------	---

Fail	Nearside Front Headlamp not working on dipped beam (1.7.5a)
-------------	---

Fail	Nearside Front Front position lamp(s) not working (1.1.A.3b)
-------------	--

MOT #2	2016-03-10 12:55
---------------	------------------

MOT test number	578926038301
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #1	2015-10-22 11:01
MOT test number	998684129017
Result	✓ Passed
Advice	Front both tyres wearing on edges



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
19 July 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	19 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2024-03-29
Current registration	 *****
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-01-07
Last registration	2023-07-17
Complete history	See info



Registration #1	2013-01-07	10 mi
Registration #2	2015-10-22	11.963 mi
Registration #3	2016-03-10	13.652 mi
Registration #4	2017-03-16	27.053 mi
Registration #5	2017-03-16	27.054 mi
Registration #6	2018-05-03	35.443 mi
Registration #7	2019-04-27	44.907 mi
Registration #8	2019-05-20	55.277 mi
Registration #9	2019-05-20	55.277 mi
Registration #10	2019-05-20	55.277 mi
Registration #11	2019-05-20	55.277 mi
Registration #12	2019-05-20	55.277 mi
Registration #13	2019-05-20	55.277 mi
Registration #14	2019-05-20	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 291601K LNQ