



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 STYLE
Colour	Silver
Year of manufacture	2002
Top speed	98 mph
0 - 60 mph	15.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	91 Nm at 2.600 rpm
Engine capacity	1.124 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	45.6 mpg
CO2 emission	148 g/km
CO2 label	F





## MOT history

MOT expiry date	2024-09-17
MOT pass rate	63 %
MOT passed	19
Failed MOT tests	11
Total advice items	45
Total items failed	24

MOT #30 2023-09-15 16:37

MOT test number 430903177426

Result ✓ Passed

Next expiry date 2024-09-17

- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #29 2023-09-15 16:05

MOT test number 788645658876

Result ✗ Failed

- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #28**

2022-09-16 12:08

**MOT test number**

745281635429

**Result**

✓ Passed

**Advice** Hydraulic brake cylinder not excessive but advise adjustment (1.1.16 (e) (i))**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**Minor** Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Power steering pipe/hose has slight seepage (2.1.5 (a))**Advice** Rear Shock absorbers has light misting of oil Both. (5.3.2 (b))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #27**

2021-09-18 14:30

**MOT test number**

729934394161

**Result**

✓ Passed

**Minor** Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Power steering ram has slight seepage from a joint (2.1.5 (a))**Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #26**

2020-10-20 10:03

**MOT test number**

194174141716

**Result**

✓ Passed

**Advice** Power steering component has slight seepage from a component (2.1.5 (a))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #25** 2020-09-21 12:09**MOT test number** 863531648422**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Parking brake inoperative on one side (1.4.1 (a))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #24** 2019-09-17 09:19**MOT test number** 110766934595**Result** ✓ Passed**MOT #23** 2019-03-07 09:55**MOT test number** 753680303807**Result** ✓ Passed**MOT #22** 2019-03-07 09:55**MOT test number** 746918361856**Result** ✗ Failed**Pass with rectification** Brake valve leaking such that brake functionality is affected valve seized (1.1.7 (d) (ii))**Pass with rectification** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**MOT #21** 2018-03-06 11:33**MOT test number** 233800957522**Result** ✓ Passed**Advice** Oil leak**Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #20** 2018-03-06 11:33**MOT test number** 814765322176**Result** ✗ Failed**Advice** Oil leak**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #19** 2017-03-07 13:28**MOT test number** 466732955902**Result** ✓ Passed**MOT #18** 2016-03-05 08:43**MOT test number** 195362276092**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #17** 2016-03-05 08:43**MOT test number** 284685608780**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**MOT #16** 2015-03-06 10:34**MOT test number** 599745065068**Result** ✓ Passed

**MOT #15**

2015-03-06 09:47

**MOT test number**

335695165012

**Result****✗ Failed**

- Pass with rectification** Offside Side repeater incorrect colour (1.4.A.2f)
- Pass with rectification** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Pass with rectification** Nearside Side repeater incorrect colour (1.4.A.2f)
- Pass with rectification** Brake load sensing valve linkage seized (3.6.E.3)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)

**MOT #14**

2014-03-05 09:41

**MOT test number**

307274564091

**Result****✓ Passed**

- Advice** Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Notice** Brake pedal has little reserve travel

**MOT #13**

2014-03-05 09:41

**MOT test number**

499424364076

**Result****✗ Failed**

- Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Notice** Brake pedal has little reserve travel
- Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)
- Advice** Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #12** 2013-03-05 11:03**MOT test number** 135584663081**Result** ✓ Passed

- Notice** Footbrake has little reserve travel.
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

**MOT #11** 2012-03-08 08:54**MOT test number** 838128762032**Result** ✓ Passed**MOT #10** 2012-03-03 12:25**MOT test number** 727813162043**Result** ✗ Failed

- Fail** Offside Rear position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Offside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #9** 2011-03-01 15:41**MOT test number** 495760961009**Result** ✓ Passed

**MOT #8** 2011-03-01 15:41**MOT test number** 757560261081**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #7** 2010-03-06 12:51**MOT test number** 594095860028**Result** ✓ Passed**MOT #6** 2010-03-05 11:16**MOT test number** 164084460472**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2009-03-06 09:37**MOT test number** 690145269088**Result** ✓ Passed**Notice** Nail in offside rear tyre**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2008-03-07 15:28**MOT test number** 440127268013**Result** ✓ Passed**MOT #3** 2007-03-06 14:15**MOT test number** 362845867092**Result** ✓ Passed



MOT #2	2006-03-03 15:44
MOT test number	343642366052
Result	✓ Passed

MOT #1	2006-03-03 09:43
MOT test number	463952366004
Result	✗ Failed
<div><div>Advice</div>Offside Front Tyre worn close to the legal limit (4.1.E.1)</div>	
<div><div>Fail</div>Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)</div>	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
17 September 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	17 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	29
First mileage registration	2002-03-08
Last registration	2023-09-15
Complete history	<a href="#">See info</a>



Registration #1	2002-03-08	8 mi
Registration #2	2006-03-03	14.180 mi
Registration #3	2006-03-03	14.182 mi
Registration #4	2007-03-06	19.828 mi
Registration #5	2008-03-07	22.669 mi
Registration #6	2009-03-06	24.960 mi
Registration #7	2010-03-05	27.432 mi
Registration #8	2010-03-06	27.432 mi
Registration #9	2011-03-01	30.741 mi
Registration #10	2012-03-03	33.405 mi
Registration #11	2012-03-08	33.405 mi
Registration #12	2013-03-05	36.018 mi
Registration #13	2014-03-05	38.498 mi
Registration #14	2015-03-06	40.057 mi
Registration #15	2015-03-06	40.057 mi
Registration #16	2016-03-01	42.117 mi
Registration #17	2016-03-01	42.117 mi
Registration #18	2016-03-01	42.117 mi
Registration #19	2016-03-01	42.117 mi
Registration #20	2016-03-01	42.117 mi
Registration #21	2016-03-01	42.117 mi
Registration #22	2016-03-01	42.117 mi
Registration #23	2016-03-01	42.117 mi
Registration #24	2016-03-01	42.117 mi
Registration #25	2016-03-01	42.117 mi
Registration #26	2016-03-01	42.117 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1432 mm
Length	3835 mm
Wheel base	2445 mm
Kerb weight	910 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	FP6G3912191