





report date: 2024-03-28

## General information

Make	PEUGEOT
Model	PARTNER HDI TEPEE S
Colour	Blue
Year of manufacture	2012
Top speed	102 mph
0 - 60 mph	14.3 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	92 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	135 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

## Entry 2

Date 2021-02-03

Pictures 8

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1

Date	2021-01-22	

Pictures 7

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



GX62CFF report date: 2024-03-28

MOT	history
-----	---------

MOT expiry date	2024-07-19
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	34
Total items failed	9

MOT #13	2023-07-20 12:03
MOT test number	363064305224
Result	✓ Passed
Next expiry date	2024-07-19

MOT #1	2	2023-02-27 11:24
MOT te	st number	828281593820
Result		✓ Passed
Advic	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advic	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #11		2022-03-07 14:50
MOT test	number	712766002281
Result		✓ Passed
Advice	Front Tyre slightly damaged/cracking or perishing Nearside & Offside (5.2.3 (d) (ii)	))
Advice	Play in steering rack inner joint(s) Nearside & Offside	
Advice	Offside Track rod end ball joint has slight play (2.1.3 (b) (i))	

MOT #10	2021-03-15 15:40
MOT test number	917970873496
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #9 2019-11-06 15:35

**MOT test number** 562936843095

MOT #8 2019-03-27 14:44

**MOT test number** 149493113003

Result Passed

**Advice** Central Exhaust mounting defective (6.1.2 (a))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Outer side wall. (5.2.3

(d) (i))

**Advice** 

**MOT #7** 2019-03-27 12:11

MOT test number 874709664049

Result X Failed

Fail Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

Rear Exhaust mounting defective Silencer. (6.1.2 (a))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Outer side wall. (5.2.3 (d) (i))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Rear Exhaust mounting defective Silencer. (6.1.2 (a))

**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Nearside and offside. (1.1.14 (a) (ii))

**Advice** Central Exhaust mounting defective (6.1.2 (a))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #6 2018-05-04 13:02 **MOT test number** 424548913226 Result ✓ Passed Advice Nearside rear tyre bald on outer edge. Offside Rear Direction indicator slightly discoloured (1.4.A.2f) Advice Advice Exhaust mounts broken centre and rear but exhaust adequately supported. Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f) Advice Nearside Rear Nail in tyre

MOT #5	2018-04-25 13:29
MOT test number	666979559345
Result	🗙 Failed
Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)	
Fail Nearside Stop lamp not working (1.2.1b)	
Advice Nearside Rear Nail in tyre	
Advice Exhaust mounts broken centre and rear but exhaust adequately supported.	
Fail Nearside Headlamp not working on dipped beam (1.7.5a)	
Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)	
Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)	
Advice Items removed from driver's view prior to test	
Advice Nearside rear tyre bald on outer edge.	

CarCheck.co.uk page 5/12



report date: 2024-03-28

MOT test number

Result

Advice Items removed from driver's view prior to test

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Advice Two rubber mounts broken on rear exhaust silencer.

Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT** #3 2017-04-26 13:13 **MOT** test number 696281197672 Result × Failed Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f) Two rubber mounts broken on rear exhaust silencer. Advice Pass with rectification Nearside Windscreen washer provides insufficient washer liquid (8.2.3) Pass with rectification Offside Rear Passenger's seat cannot be secured in the upright position. (6.2.A.2)Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f) **Advice** Items removed from driver's view prior to test Pass with rectification Offside Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #2

MOT test number

925975545494

Result

Advice
2 rubber mounts broken on rear exhaust silencer

MOT #1	2015-07-22 14:32
MOT test number	619727461832
Result	<b>✓</b> Passed

CarCheck.co.uk page 6/12



report date: 2024-03-28

# Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	19 July 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/12



GX62CFF
report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/12



More info >

report date: 2024-03-28

# Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this PEUGEOT had different number plates. ober of plates furthe scinors

CarCheck.co.uk page 9/12



GX62CFF
report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-10-05
Last registration	2023-07-20
Complete history	See info



Registration #1	2012-10-05	28 mi
Registration #2	2015-07-22	11.489 mi
Registration #3	2016-06-01	15.204 mi
Registration #4	2017-04-26	19.212 mi
Registration #5	2017-04-26	19.212 mi
Registration #6	2018-04-25	23.049 mi
Registration #7	2018-05-04	23.107 mi
Registration #8	2019-03-27	26.653 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 11/12



GX62CFF
report date: 2024-03-28

Car features

S0225	Air conditionin
S0295	
50482	
50501	
60566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	86%
Children	81%
Pedestrian	31%
Safety systems	97%
Overall rating	75%
Video	see crash video



# Dimensions & weight

Width	2112 mm
Height	1862 mm
Length	4380 mm
Wheel base	2728 mm
Max. allowed weight	2040 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12

**Engine number** 

JBEM0101385