



report date: 2025-02-13

General information

Make	MINI
Model	ONE ESTATE COOPER CLUBMAN
Colour	White
Year of manufacture	2010
Top speed	125 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.4 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D






Internet history

Entry 1

Date	2023-01-08
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-05-07
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	27
Total items failed	3

MOT #13	2024-05-08 08:25
MOT test number	705762651869
Result	✓ Passed
Next expiry date	2025-05-07

MOT #12	2024-05-08 08:25
MOT test number	766660954355
Result	✗ Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #11	2023-09-27 13:47
MOT test number	642923873840
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Stop lamp(s) non-obligatory stop lamp not working High level (4.3.1 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))



MOT #10	2023-09-27 08:12
MOT test number	650500918576
Result	✗ Failed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Stop lamp(s) non-obligatory stop lamp not working High level (4.3.1 (a) (ii))
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Offside Front Service brake excessively fluctuating (1.2.1 (e))
Advice	Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

MOT #9	2022-09-08 12:01
MOT test number	784384340003
Result	✓ Passed

MOT #8	2020-11-26 08:50
MOT test number	492686703788
Result	✓ Passed

MOT #7	2019-09-19 12:58
MOT test number	654602118324
Result	✓ Passed



MOT #6 2018-09-17 12:01

MOT test number 285775565385

Result ✔ Passed

- Advice** Offside Rear Nail in tyre
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Rear Tyre obviously under inflated (5.2.3 (h) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5 2017-09-18 16:22

MOT test number 866828190684

Result ✔ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Brake disc in poor condition
- Advice** Centre brake light not working
- Advice** Nearside Front Tyre worn close to the legal limit Worn on outer edge. (4.1.E.1)

MOT #4 2016-09-12 14:29

MOT test number 957008735084

Result ✔ Passed

MOT #3 2015-09-08 09:46

MOT test number 386471053663

Result ✔ Passed



MOT #2 2014-10-09 10:46

MOT test number 409292484297

Result ✓ Passed

Notice Wipers split

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

MOT #1 2013-10-21 13:01

MOT test number 206374793296

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 May 2025

✓
MOT

Expires:
7 May 2025

Tax status	Valid until 1 May
Days left	45
MOT expiry date	7 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Due to strict data protection laws, we cannot and do not provide the personal details of a vehicle's owner. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	YD60MDX
Plate since	2019-09-29
Current registration	YD60MDX
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-10-22
Last registration	2024-05-08
Complete history	See info



Registration #1	2010-10-22	10 mi
Registration #2	2013-10-21	19.189 mi
Registration #3	2014-10-09	30.648 mi
Registration #4	2015-09-08	38.561 mi
Registration #5	2016-09-12	44.778 mi
Registration #6	2017-09-18	51.563 mi
Registration #7	2018-09-17	69.791 mi
Registration #8	2019-09-19	68.040 mi
Registration #9	2020-05-08	68.040 mi
Registration #10	2021-05-08	68.040 mi
Registration #11	2022-05-08	68.040 mi
Registration #12	2023-05-08	68.040 mi
Registration #13	2024-05-08	68.040 mi
Registration #14	2024-05-08	68.040 mi
Registration #15	2024-05-08	68.040 mi

[More info >](#)



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1913 mm
Height	1426 mm
Length	3961 mm
Wheel base	2547 mm
Kerb weight	1145 kg
Max. allowed weight	1645 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

A4421730