



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D3 R-DESIGN
Colour	Silver
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-01-20
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-01-24
MOT pass rate	56 %
MOT passed	9
Failed MOT tests	7
Total advice items	33
Total items failed	13

MOT #16 2023-01-24 15:17

MOT test number 971586745987

Result ✓ Passed

Next expiry date 2024-01-24

- Advice** Both rear inner wheel arch corroded
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front & rear subframe corroded
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #15 2023-01-24 11:28

MOT test number 445311905206

Result ✗ Failed

- Advice** Front & rear subframe corroded
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Both rear inner wheel arch corroded
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #14** 2022-01-25 15:40**MOT test number** 956262031109**Result** ✓ Passed**MOT #13** 2022-01-24 13:53**MOT test number** 448678671874**Result** ✗ Failed**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #12** 2021-08-20 08:17**MOT test number** 305268198455**Result** ✓ Passed**Advice** Rear brake discs corroded**Advice** Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))**MOT #11** 2021-08-17 09:51**MOT test number** 635059186292**Result** ✗ Failed**Fail** Front Brakes imbalanced across an axle 35% (1.2.1 (b) (i))**Advice** Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))**Advice** Oil leak under vehicle**Fail** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** All discs corroded



MOT #10	2020-08-20 12:04
MOT test number	830191904056
Result	✓ Passed
Advice	Offside Front day time running lamp not working

MOT #9	2020-08-19 11:46
MOT test number	894613203860
Result	✗ Failed
Advice	Rear discs corroded
Fail	Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
Fail	Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
Advice	Offside Front day time running lamp not working

MOT #8	2019-07-08 14:33
MOT test number	181491207540
Result	✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2019-07-05 08:01
MOT test number	629360021230
Result	✗ Failed
Fail	Offside Rear reflector defective or damaged by more than 50% of the reflecting surface (4.8.1 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	All tyres have age related cracks
Fail	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #6** 2018-07-05 10:22**MOT test number** 852927597507**Result** ✓ Passed**Advice** Offside Rear tyre worn on inner edge**Advice** Rear disc faces corroded**Advice** Front discs corroded and front brake pads low**MOT #5** 2017-07-20 13:59**MOT test number** 532393227448**Result** ✓ Passed**MOT #4** 2017-07-18 11:15**MOT test number** 454988598585**Result** ✗ Failed**Advice** Nearside Front tyre worn on inner edge**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #3** 2016-07-15 15:23**MOT test number** 902032583222**Result** ✓ Passed**Advice** Offside Rear tyre worn on inner edge**Advice** Nearside Rear tyre worn on inner edge



MOT #2	2016-07-15 11:57
MOT test number	532703256298
Result	✗ Failed
Advice	Offside Rear tyre worn on inner edge
Fail	Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
Advice	Nearside Rear tyre worn on inner edge

MOT #1	2015-07-09 09:58
MOT test number	976630595147
Result	✓ Passed
Advice	Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✗
MOT

Expired:
24 January 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	24 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,200
Auction value	£ 19,200
Average private trade value	£ 19,200

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-07-19
Last registration	2023-01-24
Complete history	See info



Registration #1	2012-07-19	17 mi
Registration #2	2015-07-09	40.350 mi
Registration #3	2016-07-15	52.876 mi
Registration #4	2016-07-15	52.897 mi
Registration #5	2017-07-18	63.078 mi
Registration #6	2017-07-20	63.120 mi
Registration #7	2018-07-05	67.201 mi
Registration #8	2019-07-05	73.747 mi
Registration #9	2019-07-08	73.979 mi
Registration #10	2020-01-20	75.277 mi
Registration #11	2020-01-20	75.277 mi
Registration #12	2020-01-20	75.277 mi
Registration #13	2020-01-20	75.277 mi
Registration #14	2020-01-20	75.277 mi
Registration #15	2020-01-20	75.277 mi
Registration #16	2020-01-20	75.277 mi
Registration #17	2020-01-20	75.277 mi
Registration #18	2020-01-20	75.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1520 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	1115610