





report date: 2024-03-28

General information

| Make | FORD |
|---------------------|-----------------------------------|
| Model | TRANSIT CUSTOM 300 BASE P/V L1 H1 |
| Colour | White |
| Year of manufacture | 2018 |
| Top speed | 103 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 96 kW / 131 HP / 104 BHP |
|-------------------------|--------------------------|
| Max. torque | 360 Nm |
| Engine capacity | 1.995 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 38.2 mpg |
| Consumption extra urban | 47.9 mpg |
| Consumption combined | 44.1 mpg |
| CO2 emission | 167 g/km |
| CO2 label | Н |



CarCheck.co.uk page 1/11



MA68MXR report date: 2024-03-28

Internet history

Entry 1

| Date | 2021-01-31 | |
|---------------|--------------------|--|
| Pictures | 1 | |
| Listing price | <u>View report</u> | |



source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

| N/I | α | | uc: | t۸ | r\/ |
|-----|----------|----|-----|----|-----|
| 101 | • | | 115 | w | ıv |
| | • | Γh | | | . , |

| MOT expiry date | 2024-10-11 |
|--------------------|------------|
| MOT pass rate | 60 % |
| MOT passed | 3 |
| Failed MOT tests | 2 |
| Total advice items | 12 |
| Total items failed | 3 |

| MOT #5 | 2023-09-15 14:28 |
|------------------|------------------|
| MOT test number | 789787645267 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-11 |

| MOT #4 | 2023-09-14 09:01 |
|---|------------------|
| MOT test number | 484497035048 |
| Result | X Failed |
| Fail Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii)) | |
| Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #3 | | 2022-09-14 10:32 |
|----------|---|------------------|
| MOT test | number | 255823466319 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

Result

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #1 2021-10-12 07:53 **MOT** test number 661781706185 Result × Failed Nearside Windscreen wiper blade defective (3.4 (b) (i)) **Minor Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Fail Windscreen in an unacceptable condition (3.2 (c) (i)) Minor Offside Windscreen wiper blade defective (3.4 (b) (i)) **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 October |
|------------------|-----------------------|
| Days left | 155 |
| MOT expiry date | 11 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 320,00,- |
| Standard rate (6 months) | £ 176,00,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

| For how long did the current and previous owner(s) have this FORD? How many owners check it in the premium report and see all owner registrations. Download the full report | |
|---|-------------|
| | |
| ********* | |
| *************************************** | |
| ************ | |
| | |
| ********* | |
| | |
| ************* | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this FORD had different number plates. | |
| | |
| Number of plates | |
| | |
| Current registration | UK UK |
| Plate since | |
| | |
| Current registration | UK UK |
| Plate since | |
| | |
| | More info > |
| | |

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2018-09-28 |
| Last registration | 2023-09-15 |
| Complete history | See info |



| Registration #1 | 2018-09-28 | 18 mi |
|-----------------|------------|-----------|
| Registration #2 | | 11.177 es |
| Registration #3 | 2021-10-12 | 35.769 mi |
| Registration #4 | 2021-10-12 | 35.769 mi |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.117 es |
| Registration #7 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 84% |
| Children | 90% |
| Pedestrian | 48% |
| Safety systems | 71% |
| Overall rating | 76% |
| Video | see crash video |



Dimensions & weight

| Width | 2272 mm |
|---------------------|---------|
| Height | 2020 mm |
| Length | 4972 mm |
| Wheel base | 2 mm |
| Kerb weight | 1815 kg |
| Max. allowed weight | 3000 kg |

Additional information

| Fuel tank capacity | 80 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 3 page 11, |

Number of axles 2
Engine number JY11961