



**CE55HRN**

report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Black
Year of manufacture	-
Top speed	125 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	325 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg





Internet history

Entry 3

Date	2021-11-09
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 2

Date	2021-10-18
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-10-08
Pictures	14
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)



## MOT history

**MOT #20** 2022-09-20 09:12**MOT test number** 102433016701**Result** ✓ Passed**Next expiry date** 2023-09-19

**Advice** Nearside Suspension component mounting prescribed area is corroded but not considered excessive front to rear outer seal number of places (5.3.6 (a) (i))

**Advice** Offside Suspension component mounting prescribed area is corroded but not considered excessive front to rear outer seal in number of places (5.3.6 (a) (i))

**MOT #19** 2022-09-20 09:12**MOT test number** 387068968331**Result** ✗ Failed

**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))

**Advice** Offside Suspension component mounting prescribed area is corroded but not considered excessive front to rear outer seal in number of places (5.3.6 (a) (i))

**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))

**Advice** Nearside Suspension component mounting prescribed area is corroded but not considered excessive front to rear outer seal number of places (5.3.6 (a) (i))

**MOT #18** 2021-09-14 14:59**MOT test number** 203079579187**Result** ✓ Passed**MOT #17** 2021-08-04 10:00**MOT test number** 279093489546**Result** ✗ Failed

**Fail** Nearside Rear Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced hole in cill as marked (6.1.1 (c) (i))

**Fail** Headlamp levelling device cannot be operated from the driver's seat (4.1.5 (b))

**Fail** Offside Front Headlamp aim too low (4.1.2 (a))

**Fail** Offside Rear Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced hole in cill as marked (6.1.1 (c) (i))

**Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Fail** Nearside Front Headlamp aim too high (4.1.2 (a))

**MOT #16**

2020-08-20 12:50

**MOT test number**

475235681566

**Result**

✓ Passed

- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Outer Vehicle structure is corroded but structural rigidity is not significantly reduced Sill (6.1.1 (c) (i))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Outer Vehicle structure is corroded but structural rigidity is not significantly reduced Sill (6.1.1 (c) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Advise immediate replacement (5.2.3 (d) (ii))

**MOT #15**

2019-07-31 10:11

**MOT test number**

290999915652

**Result**

✓ Passed

- Advice** Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14**

2018-08-06 14:13

**MOT test number**

365282380634

**Result**

✓ Passed

**MOT #13**

2018-08-06 14:13

**MOT test number**

315843022332

**Result**

✗ Failed

- Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))
- Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))

**MOT #12** 2017-07-20 08:39**MOT test number** 417157277142**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #11** 2016-08-08 15:46**MOT test number** 192884684075**Result** ✓ Passed**Advice** Engine bay and under body covers fitted not allowing full inspection**MOT #10** 2015-09-17 10:24**MOT test number** 184537852870**Result** ✓ Passed**Advice** Rear coil spring corroded (2.4.C.1b)**Advice** Nail in nearside rear tyre**Advice** Nearside front tyre worn on edges**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Lower Suspension arm has slight play in a pin/bearing (2.4.G.2)**Advice** Nearside rear tyre has cuts in the inner sidewall**Advice** Offside front tyre worn on edges**Advice** Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2014-09-18 10:21**MOT test number** 438161164291**Result** ✓ Passed**Advice** Nearside Rear Lower Suspension arm has slight play in a pin/bearing (2.4.G.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2013-09-23 10:35**MOT test number** 186306563204**Result** ✓ Passed**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2012-09-13 11:50**MOT test number** 855717352223**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #6** 2011-09-20 11:26**MOT test number** 355873461493**Result** ✓ Passed**Notice** Front number plate damaged**MOT #5** 2011-09-15 12:07**MOT test number** 359448951251**Result** ✗ Failed**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Fail** Offside Rear Tie bar/rod has excessive play in a ball joint (2.4.G.2)**Notice** Front number plate damaged**MOT #4** 2010-09-08 11:17**MOT test number** 684951550287**Result** ✓ Passed



MOT #3	2009-09-22 13:09
MOT test number	642305469227
Result	✓ Passed
MOT #2	2008-09-24 13:45
MOT test number	641578068225
Result	✓ Passed
MOT #1	2008-08-27 11:24
MOT test number	562240148257
Result	✓ Passed





Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-28
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-09-02
Last registration	2022-09-20
Complete history	<a href="#">See info</a>



Registration #1	2005-09-02	12 mi
Registration #2	2008-08-27	60.820 mi
Registration #3	2008-09-24	61.375 mi
Registration #4	2009-09-22	74.690 mi
Registration #5	2010-09-08	85.464 mi
Registration #6	2011-09-15	92.852 mi
Registration #7	2011-09-20	92.951 mi
Registration #8	2012-09-13	99.413 mi
Registration #9	2013-09-23	104.179 mi
Registration #10	2014-09-18	107.830 mi
Registration #11	2015-09-17	112.638 mi
Registration #12	2016-08-08	117.501 mi
Registration #13	2016-08-08	117.501 mi
Registration #14	2016-08-08	117.501 mi
Registration #15	2016-08-08	117.501 mi
Registration #16	2016-08-08	117.501 mi
Registration #17	2016-08-08	117.501 mi
Registration #18	2016-08-08	117.501 mi
Registration #19	2016-08-08	117.501 mi
Registration #20	2016-08-08	117.501 mi
Registration #21	2016-08-08	117.501 mi
Registration #22	2016-08-08	117.501 mi
Registration #23	2016-08-08	117.501 mi
Registration #24	2016-08-08	117.501 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2015 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	0502162050516G