



HYUNDAI



report date: 2024-03-29

General information

| | |
|---------------------|------------------------|
| Make | HYUNDAI |
| Model | I30 CRDI SE BLUE DRIVE |
| Colour | Grey |
| Year of manufacture | 2015 |
| Top speed | 117 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 109 BHP |
| Max. torque | 280 Nm at 1.500 rpm |
| Engine capacity | 1.582 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 67.3 mpg |
| Consumption extra urban | 83.1 mpg |
| Consumption combined | 78.5 mpg |
| CO2 emission | 94 g/km |
| CO2 label | A |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-31 |
| Pictures | 3 |
| Listing price | View report |



source: [autoonline.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-11-26 |
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 15 |
| Total items failed | 4 |

| | |
|------------------|---|
| MOT #8 | 2023-11-20 11:59 |
| MOT test number | 972157010374 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-26 |
| Advice | Tyre waring light on dash |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|--|
| MOT #7 | 2022-11-24 15:41 |
| MOT test number | 902296525840 |
| Result | ✓ Passed |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |

| | |
|-----------------|---|
| MOT #6 | 2022-11-21 17:01 |
| MOT test number | 571278928247 |
| Result | ✗ Failed |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Offside Front worn on edges |
| Fail | Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h)) |
| Advice | Nearside Front tyre worn on edges |

**MOT #5** 2021-11-26 10:07**MOT test number** 219706227536**Result** ✓ Passed**MOT #4** 2020-11-26 12:15**MOT test number** 448766579547**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracks in tread (5.2.3 (d) (ii))**MOT #3** 2019-11-22 09:57**MOT test number** 199826730375**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #2** 2018-11-26 10:03**MOT test number** 593926358574**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Child Seat fitted not allowing full inspection of adult belt



MOT #12018-11-26 10:03

MOT test number643460937323

| Result | | ✗ Failed |
|-------------------------|---|----------|
| Pass with rectification | Nearside Headlamp aim too low and too far to the right. (4.1.2 (a)) | |
| Pass with rectification | Windscreen washer provides insufficient washer liquid (3.5 (a)) | |
| Advice | Child Seat fitted not allowing full inspection of adult belt | |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Pass with rectification | Offside Headlamp aim too high (4.1.2 (a)) | |



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
26 November 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 April |
| Days left | 336 |
| MOT expiry date | 26 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,200 |
| Auction value | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

| | |
|----------------------|---|
| Number of plates | 1 |
| Current registration |   |
| Plate since | 2024-03-29 |
| Current registration |   |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 10 |
| First mileage registration | 2015-11-27 |
| Last registration | 2023-11-20 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2015-11-27 | 27 mi |
| Registration #2 | 2018-11-26 | 35.912 mi |
| Registration #3 | 2018-11-26 | 35.912 mi |
| Registration #4 | 2019-11-22 | 48.205 mi |
| Registration #5 | 2020-11-26 | 55.430 mi |
| Registration #6 | 2020-11-26 | 55.430 mi |
| Registration #7 | 2020-11-26 | 55.430 mi |
| Registration #8 | 2020-11-26 | 55.430 mi |
| Registration #9 | 2020-11-26 | 55.430 mi |
| Registration #10 | 2020-11-26 | 55.430 mi |

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 90% |
| Children | 90% |
| Pedestrian | 67% |
| Safety systems | 86% |
| Overall rating | 85% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1780 mm |
| Height | 1470 mm |
| Length | 4300 mm |
| Wheel base | 2650 mm |
| Kerb weight | 1429 kg |
| Max. allowed weight | 1920 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 53 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|--------------|
| Number of axles | 2 |
| Engine number | D4FBFZ066893 |