




report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVARO L2H1 2900 SPORTIVE CDTI
Colour	Silver
Year of manufacture	2018
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	47.1 mpg
Consumption combined	42.2 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-12-18
Pictures	4
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-15
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	12
Total items failed	6

MOT #4	2023-10-16 15:06
MOT test number	234689053240
Result	✓ Passed
Next expiry date	2024-10-15
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Coolant on minimum
Advice	Brake pedal wearing smooth (1.1.2 (c))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #3**

2023-10-13 14:16

MOT test number

959384522265

Result**✗ Failed**

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Front Anti-roll bar linkage ball joint has slight play n/s & o/s (5.3.4 (a) (i))
- Advice** Nearside Rear Nail in tyre
- Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Coolant on minimum
- Fail** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer edge (5.2.3 (d) (i))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #2

2022-09-29 10:35

MOT test number

269360155988

Result**✓ Passed****MOT #1**

2021-09-04 11:51

MOT test number

289225319656

Result**✓ Passed**



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
15 October 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	15 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 DS18KCK
Plate since	2019-03-28
Current registration	 DS18KCK
Plate since	2019-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-06-30
Last registration	2023-10-16
Complete history	See info



Registration #1	2018-06-30	11 mi
Registration #2	2021-09-04	68.358 mi
Registration #3	2023-06-20	75.277 mi
Registration #4	2023-06-20	75.277 mi
Registration #5	2023-06-20	75.277 mi
Registration #6	2023-06-20	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1750 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M H4 - C158668LWZ