



SL09ZST

report date: 2024-03-28

General information

Make	FIAT
Model	GRANDE PUNTO ACTIVE
Colour	Grey
Year of manufacture	2009
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-11-04
Pictures	17
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-08
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	37
Total items failed	17

MOT #18	2024-02-08 17:56
MOT test number	188498896063
Result	✓ Passed
Next expiry date	2025-02-08
Advice	Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Minor	Nearside Front Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #17**

2024-02-08 14:03

MOT test number

797179439686

Result

✗ Failed

- Minor** Nearside Front Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Rear Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #16

2023-02-09 16:08

MOT test number

716494711729

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #15**

2023-02-09 16:08

MOT test number

941651793816

Result**✗ Failed****Advice**

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification

Nearside Front Position lamp not working (4.2.1 (a) (ii))

Minor

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification

Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Minor

Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #14

2022-01-20 13:24

MOT test number

493891962025

Result**✓ Passed**

**MOT #13**

2022-01-18 14:37

MOT test number

645302157461

Result**✗ Failed**

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Emissions not tested (8.2.1.2 (d))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm 175 65 15 (5.2.3 (e))
- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Windscreen wiper does not clear the windscreen effectively TO BE TESTED (3.4 (b) (ii))
- Fail** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #12

2021-01-08 09:22

MOT test number

460349420145

Result**✓ Passed**

- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Tyre slightly damaged/cracking or perishing Offside and nearside (5.2.3 (d) (ii))
- Advice** Front Sub-frame corroded but not seriously weakened and suspension arms (5.3.3 (b) (i))

**MOT #11** 2019-12-30 09:12**MOT test number** 261970483996**Result** ✓ Passed**Advice** Slight corrosion to front subframe**Advice** Rear Coil spring corroded (5.3.1 (b) (i))**MOT #10** 2019-01-28 12:56**MOT test number** 997110790638**Result** ✓ Passed**MOT #9** 2018-12-06 10:08**MOT test number** 957028706710**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2018-02-01 15:31**MOT test number** 330204742393**Result** ✓ Passed**MOT #7** 2017-02-06 10:12**MOT test number** 651098526033**Result** ✓ Passed

**MOT #6** 2016-02-09 13:04**MOT test number** 426486839873**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Rear tyres slight cracking**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front tyres wearing on inner edge**MOT #5** 2016-02-09 09:39**MOT test number** 649075373781**Result** ✗ Failed**Advice** Rear tyres slight cracking**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front tyres wearing on inner edge**Fail** Front Windscreen wiper does not clear the windscreen effectively Both (8.2.2)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #4** 2015-01-19 09:09**MOT test number** 117829815015**Result** ✓ Passed**Notice** Exhaust corrded**Notice** Rear tyres slight cracking**MOT #3** 2014-01-23 17:18**MOT test number** 586593524063**Result** ✓ Passed



MOT #2	2013-05-21 13:48
MOT test number	417341943136
Result	✓ Passed
MOT #1	2012-05-22 08:54
MOT test number	235933542109
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
8 February 2025

Tax status	Valid until 1 September
Days left	126
MOT expiry date	8 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-05-28
Last registration	2024-02-08
Complete history	See info



Registration #1	2009-05-28	14 mi
Registration #2	2012-05-22	16.119 mi
Registration #3	2013-05-21	21.152 mi
Registration #4	2014-01-23	22.386 mi
Registration #5	2015-01-19	28.776 mi
Registration #6	2016-02-09	36.258 mi
Registration #7	2016-02-09	36.258 mi
Registration #8	2017-02-06	44.549 mi
Registration #9	2018-02-01	54.988 mi
Registration #10	2018-12-06	63.075 mi
Registration #11	2019-05-22	71.277 mi
Registration #12	2019-05-22	71.277 mi
Registration #13	2019-05-22	71.277 mi
Registration #14	2019-05-22	71.277 mi
Registration #15	2019-05-22	71.277 mi
Registration #16	2019-05-22	71.277 mi
Registration #17	2019-05-22	71.277 mi
Registration #18	2019-05-22	71.277 mi
Registration #19	2019-05-22	71.277 mi
Registration #20	2019-05-22	71.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9519694