



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SPORT 5 STR
Colour	Grey
Year of manufacture	2007
Top speed	122 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-23
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2025-03-26
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	28
Total items failed	4

MOT #18	2024-02-29 14:11
MOT test number	698437838273
Result	✓ Passed
Next expiry date	2025-03-26

MOT #17	2024-02-28 15:07
MOT test number	762812377016
Result	✗ Failed
Fail	Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #16	2023-03-20 11:02
MOT test number	400894978878
Result	✓ Passed
Advice	Coil spring corroded both front (5.3.1 (b) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #15**

2022-03-22 10:23

**MOT test number**

401860208041

**Result**

✓ Passed

- Advice** Nearside Rear NSR bump stop split
- Advice** Offside Front OSF suspension spring corroded
- Advice** Offside Rear OSR suspension spring corroded
- Advice** Offside OS mirror repeater mouldy (but still in working order)
- Advice** Offside Rear OSR bump stop split
- Advice** Nearside Front NSF suspension spring corroded
- Advice** Nearside Rear NSR suspension spring corroded
- Advice** Nearside NS mirror repeater mouldy (but still in working order)

**MOT #14**

2021-03-27 12:37

**MOT test number**

873950188072

**Result**

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 205/55/16 (5.2.3 (e))
- Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2020-03-23 10:06

**MOT test number**

368376382860

**Result**

✓ Passed

- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #12** 2020-03-21 13:54**MOT test number** 351573012173**Result** ✗ Failed**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #11** 2019-02-01 14:42**MOT test number** 697492471803**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2018-01-30 16:23**MOT test number** 652051723104**Result** ✓ Passed**Advice** Front Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit worn on inner edge (4.1.E.1)**MOT #9** 2017-01-25 16:35**MOT test number** 513220046838**Result** ✓ Passed**MOT #8** 2016-02-01 11:51**MOT test number** 647610636214**Result** ✓ Passed

**MOT #7** 2015-03-19 14:32**MOT test number** 176408875413**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #6** 2014-03-28 13:34**MOT test number** 158067984462**Result** ✓ Passed**MOT #5** 2013-03-28 12:16**MOT test number** 897197483077**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Screenwash pipe split**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-03-16 15:01**MOT test number** 368526572028**Result** ✓ Passed**MOT #3** 2012-03-16 15:01**MOT test number** 677686372093**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #2** 2011-03-18 16:55**MOT test number** 578627971075**Result** ✓ Passed



MOT #1	2010-03-19 13:16
MOT test number	353568070056
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 May 2024

✓  
**MOT**  
  
Expires:  
26 March 2025

Tax status	Valid until 1 May
Days left	2
MOT expiry date	26 March 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>GJ07WVR</b>
Plate since	2019-03-28
Current registration	 <b>GJ07WVR</b>
Plate since	2019-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-31
Last registration	2024-02-29
Complete history	<a href="#">See info</a>



Registration #1	2007-03-31	6 mi
Registration #2	2010-03-19	22.429 mi
Registration #3	2011-03-18	28.974 mi
Registration #4	2012-03-16	34.576 mi
Registration #5	2013-03-28	41.337 mi
Registration #6	2014-03-28	46.883 mi
Registration #7	2015-03-19	51.555 mi
Registration #8	2016-02-01	55.594 mi
Registration #9	2017-01-25	69.761 mi
Registration #10	2018-01-30	82.427 mi
Registration #11	2019-01-29	95.557 mi
Registration #12	2020-01-29	108.687 mi
Registration #13	2021-01-29	121.817 mi
Registration #14	2022-01-29	134.947 mi
Registration #15	2023-01-29	148.077 mi
Registration #16	2024-01-29	161.207 mi
Registration #17	2025-01-29	174.337 mi
Registration #18	2026-01-29	187.467 mi
Registration #19	2027-01-29	200.597 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1561 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BKD B25746