



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D DRIVE R-DESIGN
Colour	White
Year of manufacture	2010
Top speed	118 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-10-24
Pictures	7
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-13
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	28
Total items failed	0

MOT #14	2023-07-14 15:21
MOT test number	690350252974
Result	✓ Passed
Next expiry date	2024-07-13
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Service brake binding but not excessively (1.2.1 (f))

MOT #13	2022-05-27 09:14
MOT test number	813165563112
Result	✓ Passed

MOT #12	2022-05-25 10:38
MOT test number	670049281272
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
MAJOR	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
DANGEROUS	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
MAJOR	Nearside Headlamp aim too high (4.1.2 (a))
MAJOR	Offside Rear Direction indicator incorrect colour (4.4.3 (a))

**MOT #11** 2021-05-17 13:52**MOT test number** 676157227096**Result** ✓ Passed**MOT #10** 2020-06-29 14:24**MOT test number** 486897176653**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Drive belt cracked**MOT #9** 2020-06-26 16:05**MOT test number** 687553651079**Result** ✗ Failed**Advice** Drive belt cracked**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2019-06-25 10:30**MOT test number** 492258413086**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2019-06-24 08:31**MOT test number** 733986695510**Result** ✗ Failed**MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #6** 2018-06-20 15:06**MOT test number** 193034583734**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #5** 2017-06-20 15:44**MOT test number** 962356866203**Result** ✓ Passed**MOT #4** 2016-06-22 08:23**MOT test number** 667864471656**Result** ✓ Passed



MOT #3	2015-06-23 09:16
MOT test number	776474175125
Result	✓ Passed
MOT #2	2014-07-01 16:36
MOT test number	208972784173
Result	✓ Passed
MOT #1	2013-11-26 09:49
MOT test number	788790033384
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
13 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	13 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2023-03-28
Current registration	 
Plate since	2023-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-06-29
Last registration	2023-07-14
Complete history	See info



Registration #1	2010-06-29	15 mi
Registration #2	2013-11-26	42.864 mi
Registration #3	2014-07-01	47.443 mi
Registration #4	2015-06-23	64.433 mi
Registration #5	2016-06-22	81.670 mi
Registration #6	2017-06-20	88.457 mi
Registration #7	2018-06-20	94.253 mi
Registration #8	2019-06-24	100.788 mi
Registration #9	2020-06-29	107.323 mi
Registration #10	2021-06-29	113.858 mi
Registration #11	2022-06-29	120.393 mi
Registration #12	2023-06-29	126.928 mi
Registration #13	2024-06-29	133.463 mi
Registration #14	2025-06-29	140.000 mi
Registration #15	2026-06-29	146.537 mi
Registration #16	2027-06-29	153.074 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1381 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	960306