



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	407 HDI SE
Colour	Gold
Year of manufacture	-
Top speed	129 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-09
Pictures	17
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #21</b>	2021-09-27 15:42
<b>MOT test number</b>	535508559377
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-10-02
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Minor</b>	Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
<b>Advice</b>	Play in steering rack inner joint(s) n/s

<b>MOT #20</b>	2021-09-24 10:28
<b>MOT test number</b>	859448981602
<b>Result</b>	✗ Failed
<b>DANGEROUS</b>	Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
<b>MAJOR</b>	Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))
<b>MAJOR</b>	Nearside Windscreen washer not working (3.5 (a))
<b>MAJOR</b>	Offside Windscreen washer not working (3.5 (a))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Minor</b>	Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
<b>Advice</b>	Play in steering rack inner joint(s) n/s

<b>MOT #19</b>	2020-09-30 13:21
<b>MOT test number</b>	263339557063
<b>Result</b>	✓ Passed
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Play in steering rack inner joint(s)

**MOT #18** 2020-09-30 12:19**MOT test number** 204425139213**Result** ✗ Failed**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Play in steering rack inner joint(s)**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Tyre worn close to legal limit/worn on edge ALL 4 (5.2.3 (e))**MOT #17** 2019-10-03 07:56**MOT test number** 186298171672**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Play in steering rack inner joint(s)**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #16** 2018-10-01 14:02**MOT test number** 659740804014**Result** ✓ Passed**MOT #15** 2017-09-28 14:55**MOT test number** 693199922974**Result** ✓ Passed**Advice** Front registration plate cracked**Advice** Slight play in n/s front wheel

**MOT #14**

2016-09-28 09:09

**MOT test number**

141032329043

**Result**

✓ Passed

**Advice** Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #13**

2015-09-24 08:12

**MOT test number**

415754337720

**Result**

✓ Passed

**Advice** Inner edge of o/s front tyre tread worn**Advice** N/s rear light lens cracked**Advice** Front registration plate cracked**Advice** Slight play in n/s front wheel**Advice** Child seat fitted not allowing full inspection of adult seat belt**Advice** O/s dip beam bulb dim



MOT #12

2014-09-26 16:06

MOT test number

935769464249

Result

✓ Passed

- Notice

Nail in nearside rear tyre
- Notice

No lights fitted at time of test
- Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice

Play in steering rack inner joint(s)
- Notice

Child seat fitted not allowing full inspection of adult belt
- Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice

Under-trays fitted obscuring some underside components



MOT #11

2014-09-26 09:20

MOT test number

215299064208

Result		✗ Failed
Fail	Offside Rear Direction indicator not working (1.4.A.2c)	
Fail	Offside Rear position lamp(s) not working (1.1.A.3b)	
Notice	Nail in nearside rear tyre	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Fail	Offside Registration plate lamp not working (1.1.C.1d)	
Notice	No lights fitted at time of test	
Fail	Offside Stop lamp not working (1.2.1b)	
Notice	Play in steering rack inner joint(s)	
Fail	Nearside Rear Direction indicator not working (1.4.A.2c)	
Fail	Nearside Rear position lamp(s) not working (1.1.A.3b)	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Fail	Nearside Registration plate lamp not working (1.1.C.1d)	
Notice	Child seat fitted not allowing full inspection of adult belt	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail	Nearside Stop lamp not working (1.2.1b)	
Notice	Under-trays fitted obscuring some underside components	
Fail	Rear fog lamp not working (1.3.2b)	

**MOT #10** 2013-09-27 16:59**MOT test number** 126860873236**Result** ✓ Passed**Notice** Slight play in n/s front wheel**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #9** 2013-09-27 10:07**MOT test number** 447810173214**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Slight play in n/s front wheel**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2012-09-28 11:40**MOT test number** 938622272227**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Inner edge of both front tyres getting worn



**MOT #7**

2012-09-28 09:27

**MOT test number**

358412672280

**Result****✗ Failed**

- Notice** Inner edge of both front tyres getting worn
- Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Offside Headlamp aim too high (1.8)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Nearside Headlamp aim too high (1.8)

**MOT #6**

2011-09-27 14:27

**MOT test number**

555720771250

**Result****✓ Passed****MOT #5**

2011-09-27 11:43

**MOT test number**

107600271235

**Result****✗ Failed**

- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #4**

2010-09-27 09:54

**MOT test number**

370810370443

**Result****✓ Passed**

- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Poor operation n/s washer jet



<b>MOT #3</b>	2009-09-07 14:55
<b>MOT test number</b>	610270459293
<b>Result</b>	✓ Passed
<b>Advice</b>	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

<b>MOT #2</b>	2009-09-07 13:11
<b>MOT test number</b>	651850359253
<b>Result</b>	✗ Failed
<b>Advice</b>	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Fail</b>	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

<b>MOT #1</b>	2009-09-01 16:50
<b>MOT test number</b>	722484449277
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
<b>Notice</b>	Got cuts in o/s/r outer sidewall
<b>Fail</b>	Offside Front Headlamp aim too high (1.8)
<b>Advice</b>	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Fail</b>	Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
<b>Fail</b>	Nearside Front Headlamp aim too high (1.8)
<b>Advice</b>	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	 <b>KP56BHJ</b>
Plate since	2019-09-28
Current registration	 <b>KP56BHJ</b>
Plate since	2019-09-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-09-30
Last registration	2021-09-27
Complete history	<a href="#">See info</a>



Registration #1	2006-09-30	26 mi
Registration #2	2009-09-01	33.678 mi
Registration #3	2009-09-07	33.819 mi
Registration #4	2009-09-07	33.819 mi
Registration #5	2010-09-27	43.654 mi
Registration #6	2011-09-27	49.825 mi
Registration #7	2011-09-27	49.828 mi
Registration #8	2012-09-28	57.163 mi
Registration #9	2012-09-28	57.165 mi
Registration #10	2013-09-27	64.815 mi
Registration #11	2013-09-27	64.818 mi
Registration #12	2014-09-26	74.254 mi
Registration #13	2015-09-27	81.257 mi
Registration #14	2015-09-27	81.257 mi
Registration #15	2015-09-27	81.257 mi
Registration #16	2015-09-27	81.257 mi
Registration #17	2015-09-27	81.257 mi
Registration #18	2015-09-27	81.257 mi
Registration #19	2015-09-27	81.257 mi
Registration #20	2015-09-27	81.257 mi
Registration #21	2015-09-27	81.257 mi
Registration #22	2015-09-27	81.257 mi
Registration #23	2015-09-27	81.257 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1811 mm
Height	1455 mm
Length	4676 mm
Wheel base	2725 mm
Kerb weight	1580 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5



<b>Number of axles</b>	2
<b>Engine number</b>	DYVD4049110